



SERVICE BULLETIN

Classification: EM19-003	Reference: NTB19-041	Date: May 8, 2019
-----------------------------	-------------------------	----------------------

2019 ALTIMA; CREAK OR POP NOISE WHEN TURNING AND ACCELERATING OR DECELERATING

- APPLIED VEHICLES:** 2019 Altima (L34)
APPLIED ENGINE: 2.5L (PR25DD) engine ONLY
APPLIED VIN // DATE: Vehicles built before 1N4*L4A**KC 210080 // March 12, 2019
Vehicles built before 1N4*L4A**KN 323741 // March 11, 2019

IF YOU CONFIRM

A creak or pop noise is heard from the front of the vehicle when turning right while accelerating or decelerating.

ACTION

Replace the engine mounting insulator (LH) with the one listed in the **PARTS INFORMATION**.

- For the procedure to replace the engine mounting insulator (LH) refer to the Electronic Service Manual (ESM): section **REPAIR > ENGINE > ENGINE MECHANICAL > REMOVAL AND INSTALLATION > ENGINE MOUNTING INSULATOR (LH)**

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
Engine mounting insulator (LH)	11220- 6CA0B	1

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
RPL LH Insulator Mount	(1)	AW57AA	ZL	32	(2)

- (1) Reference the electronic parts catalog, and use the Engine Mount (11220-*****) as the Primary Failed Part (PFP).
- (2) Reference the current Nissan Warranty Flat Rate Manual and use the indicated Flat Rate Time (FRT).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
May 8, 2019	NTB19-041	Original bulletin published

