

RC-19-84-01

MODEL: 2018 Karma Revero DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)

PRIORITY: Revero vehicles in the attached list (PP. 3~4)

APPLICABILITY: 2018 Karma Revero

MARKET REGIONS: United States and Canada

PURPOSE: This document highlights the removal of the Airbag Control Unit (ACU) Assembly and

installation of the new provided part.

This document supersedes any and all previous documents in workshop manuals, wiring diagrams, training documents, parts catalog, labor operations, etc. While the method of repair is approved as indicated, performing and verifying the repair is proper is the responsibility of the technician.

Safety Recall Notice (Remedy) 2018 Model Year Karma Revero - Airbag Control Unit Important Information Enclosed

IMPORTANT REMINDER ON VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS

New Vehicles in Dealer Inventory: It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.

Pre-Owned Vehicles in Dealer Inventory: Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.

Have a camera available and ready. Capture images of the removed airbag control module assembly, and the new airbag control module assembly, prior to installation. These images showing both serial numbers (clearly and readable) must be attached to the recall warranty claim, the TSS case, and retained with repair order documentation, as well. This is needed for the NHTSA and Transport Canada recall records.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 1 of 17 Published: June 2019



RC-19-84-01

MODEL: 2018 Karma Revero

DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)

TOOLS REQUIRED: All component removal MUST be performed using hand tools.



T30 torx bit



7mm socket




1/4" Extension



Torque Wrench



Pick Tools



Trim Removal Tools



Camera or image capturing device such as a camera equipped mobile phone

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 2 of 17 Published: June 2019



RC-19-84-01

MODEL: 2018 Karma Revero

DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)

50GK41SA5JA000003	50GK41SAXJA000109	50GK41SA0JA000149	50GK41SA8JA000187
50GK41SA9JA000005	50GK41SA6JA000110	50GK41SA9JA000151	50GK41SAXJA000188
50GK41SA4JA000008	50GK41SAXJA000112	50GK41SA0JA000152	50GK41SA1JA000189
50GK41SA7JA000018	50GK41SA1JA000113	50GK41SA2JA000153	50GK41SA8JA000190
50GK41SA5JA000051	50GK41SA3JA000114	50GK41SA4JA000154	50GK41SAXJA000191
50GK41SA9JA000053	50GK41SA5JA000115	50GK41SAXJA000157	50GK41SA1JA000192
50GK41SA5JA000065	50GK41SA7JA000116	50GK41SA1JA000158	50GK41SA3JA000193
50GK41SA6JA000074	50GK41SA9JA000117	50GK41SA3JA000159	50GK41SA5JA000194
50GK41SA3JA000078	50GK41SA0JA000118	50GK41SAXJA000160	50GK41SA7JA000195
50GK41SA5JA000079	50GK41SA2JA000119	50GK41SA1JA000161	50GK41SA9JA000196
50GK41SA1JA000080	50GK41SA9JA000120	50GK41SA3JA000162	50GK41SA0JA000197
50GK41SA3JA000081	50GK41SA0JA000121	50GK41SA5JA000163	50GK41SA2JA000198
50GK41SA5JA000082	50GK41SA2JA000122	50GK41SA9JA000165	50GK41SA4JA000199
50GK41SA0JA000085	50GK41SA4JA000123	50GK41SA0JA000166	50GK41SA7JA000200
50GK41SA2JA000086	50GK41SA6JA000124	50GK41SA2JA000167	50GK41SA9JA000201
50GK41SA4JA000087	50GK41SAXJA000126	50GK41SA4JA000168	50GK41SA0JA000202
50GK41SA6JA000088	50GK41SA1JA000127	50GK41SA6JA000169	50GK41SA2JA000203
50GK41SA8JA000089	50GK41SA3JA000131	50GK41SA2JA000170	50GK41SA4JA000204
50GK41SA4JA000090	50GK41SA5JA000132	50GK41SA4JA000171	50GK41SA6JA000205
50GK41SA6JA000091	50GK41SA7JA000133	50GK41SA6JA000172	50GK41SA8JA000206
50GK41SA8JA000092	50GK41SA9JA000134	50GK41SA8JA000173	50GK41SAXJA000207
50GK41SAXJA000093	50GK41SA0JA000135	50GK41SAXJA000174	50GK41SA1JA000208
50GK41SA1JA000094	50GK41SA2JA000136	50GK41SA1JA000175	50GK41SA3JA000209
50GK41SA3JA000095	50GK41SA4JA000137	50GK41SA3JA000176	50GK41SAXJA000210
50GK41SA5JA000096	50GK41SA6JA000138	50GK41SA7JA000178	50GK41SA1JA000211
50GK41SA7JA000097	50GK41SA8JA000139	50GK41SA9JA000179	50GK41SA3JA000212
50GK41SA9JA000098	50GK41SA4JA000140	50GK41SA5JA000180	50GK41SA5JA000213
50GK41SA5JA000101	50GK41SA8JA000142	50GK41SA9JA000182	50GK41SA7JA000214
50GK41SA9JA000103	50GK41SAXJA000143	50GK41SA0JA000183	50GK41SA9JA000215
50GK41SA0JA000104	50GK41SA1JA000144	50GK41SA2JA000184	50GK41SA0JA000216
50GK41SA6JA000107	50GK41SA7JA000147	50GK41SA4JA000185	50GK41SA2JA000217
50GK41SA8JA000108	50GK41SA9JA000148	50GK41SA6JA000186	50GK41SA6JA000219

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 3 of 17 Published: June 2019



RC-19-84-01

MODEL: 2018 Karma Revero

DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)

	50GK41SA2JA000220	50GK41SA5JA000258	50GK41SA6JA000298	50GK4LSA4JAA00007
	50GK41SA4JA000221	50GK41SA7JA000259	50GK41SA8JA000299	50GK4LSA6JAA00008
ĺ	50GK41SA8JA000223	50GK41SA3JA000260	50GK41SA0JA000300	50GK4LSA4JAA00010
Ì	50GK41SAXJA000224	50GK41SA5JA000261	50GK41SA2JA000301	50GK4LSA6JAA00011
	50GK41SA1JA000225	50GK41SA7JA000262	50GK41SA6JA000303	50GK4LSA8JAA00012
Ì	50GK41SA3JA000226	50GK41SA9JA000263	50GK41SA8JA000304	50GK4LSA1JAA00014
ĺ	50GK41SA5JA000227	50GK41SA0JA000264	50GK41SAXJA000305	50GK4LSA3JAA00015
ĺ	50GK41SA7JA000228	50GK41SA2JA000265	50GK41SA1JA000306	50GK4LSA8JAA00009
Ì	50GK41SA9JA000229	50GK41SA4JA000266	50GK41SA3JA000307	50GK4LSAXJAA00013
ĺ	50GK41SA7JA000231	50GK41SA6JA000267	50GK41SA5JA000308	
Ì	50GK41SA9JA000232	50GK41SA8JA000268	50GK41SA3JA000310	
Ì	50GK41SA2JA000234	50GK41SAXJA000269	50GK41SA5JA000311	
ĺ	50GK41SA4JA000235	50GK41SA6JA000270	50GK41SA7JA000312	
Ì	50GK41SA6JA000236	50GK41SA8JA000271	50GK41SA9JA000313	
ĺ	50GK41SAXJA000238	50GK41SAXJA000272	50GK41SA0JA000314	
ĺ	50GK41SA8JA000240	50GK41SA1JA000273	50GK41SA2JA000315	
Ì	50GK41SAXJA000241	50GK41SA3JA000274	50GK41SA4JA000316	
ĺ	50GK41SA3JA000243	50GK41SA7JA000276	50GK41SA6JA000317	
Ì	50GK41SA5JA000244	50GK41SA2JA000279	50GK41SA8JA000318	
ĺ	50GK41SA7JA000245	50GK41SA9JA000280	50GK41SAXJA000319	
	50GK41SA9JA000246	50GK41SA0JA000281	50GK41SA6JA000320	
ĺ	50GK41SA0JA000247	50GK41SA2JA000282	50GK41SA8JA000321	
Ì	50GK41SA2JA000248	50GK41SA6JA000284	50GK41SAXJA000322	
	50GK41SA4JA000249	50GK41SA8JA000285	50GK41SA1JA000323	
	50GK41SA0JA000250	50GK41SAXJA000286	50GK41SA3JA000324	
	50GK41SA2JA000251	50GK41SA1JA000287	50GK41SA5JA000325	
	50GK41SA4JA000252	50GK41SA5JA000289	50GK4LSA3JAA00001	
	50GK41SA6JA000253	50GK41SA1JA000290	50GK4LSA5JAA00002	
	50GK41SA8JA000254	50GK41SA3JA000291	50GK4LSA7JAA00003	
ĺ	50GK41SAXJA000255	50GK41SA5JA000292	50GK4LSA9JAA00004	
Ì	50GK41SA1JA000256	50GK41SA7JA000293	50GK4LSA0JAA00005	
	50GK41SA3JA000257	50GK41SA0JA000295	50GK4LSA2JAA00006	

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 4 of 17 Published: June 2019



RC-19-84-01

MODEL: 2018 Karma Revero

DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)


1. Remove solar panel fuse (#10) from the fuse block, as shown in Figure 1.

△ NOTICE!

Prior to performing the 12-volt disconnect procedure, make sure to record the radio presets.



2. Perform the 12-Volt disconnect procedure (Fig. 2).



3. Remove the triangular trim pieces from the left and right sides of the center console, as shown in Figure 3.



To prevent damage to the dash trim pieces, use only non-marring, plastic, trim removal tools.



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 5 of 17 Published: June 2019



RC-19-84-01

MODEL: 2018 Karma Revero

DATE: June 2019

Released-June 2019

MODEL. 2010 Railia Revelo

TITLE: Remedy, Replacement Airbag Control Unit (ACU)

4. Remove the jewel trim piece from the dash, as shown in Figure 4.

△ CAUTION!

To prevent damage to the finish of the jewel piece, or the dash, use only non-marring, plastic, trim removal tools.



5. Carefully remove three (3) connectors from the back of the dash jewel trim piece (Fig. 5). **NOTE:** Place the dash jewel trim piece in a safe place.



6. Remove the jewel trim piece from the center console, as shown in Figure 6. **NOTE: Place the center console jewel trim piece in a safe place.**

△ CAUTION!

To prevent damage to the finish of the jewel trim pieces, or the console, use only non-marring, plastic, trim removal tools.



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 6 of 17 Published: June 2019



RC-19-84-01

MODEL: 2018 Karma Revero

DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)

7. Remove two (2) Torx-head screws from the rear-most mounting location of the center console, as shown in Figure 7.



8. Open the center console storage compartment lid (Fig. 8).



9. Use a pick-tool to carefully remove two (2) felt-trimmed covers from the leading edge of the center console storage compartment, as shown in Figure 9.



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 7 of 17 Published: June 2019



RC-19-84-01

MODEL: 2018 Karma Revero

DATE: June 2019


Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)


10. Remove two (2) Torx-head screws from the leading edge of the center console storage compartment, as shown in Figure 10.



11. Remove two (2) Hex-bolts securing the center console to the dashboard, as shown in Figure 11.



12. Remove two (2) Hex-bolts securing the center console to the dashboard above the Touch Panel Inteface (TPI), as shown in Figure 12.



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 8 of 17 Published: June 2019



RC-19-84-01


MODEL: 2018 Karma Revero

DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)


13. Apply pressure to the right side of the center console and pull up in order to release the mounting clip, as shown in Figure 13.



14. Grasp the center console with both hands and carefully pull it away from the dashboard, as shown in Figure 14.



15. Carefully disconnect all connectors at the back of the Touch Panel Interface (TPI), as shown in Figure 15.



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 9 of 17 Published: June 2019



RC-19-84-01


MODEL: 2018 Karma Revero

DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)


16. Carefully disconnect all the connectors at the trailing edge of the center console, as shown in Figure 16.



17. Carefully lift and place the center console on its side. Undo any clips securing the harnesses to the bottom of the center console, as shown in Figure 17.



18. Carefully move all TPI harnesses away from the Airbag Control Unit (ACU), as shown in Figure 18.



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 10 of 17 Published: June 2019



RC-19-84-01

MODEL: 2018 Karma Revero

DATE: June 2019


Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)


19. Remove four (4) Torx-head screws from the ACU (Fig. 19).



20. Gently pull the Airbag Control Unit (ACU) away from the mounting location on the battery tunnel, as shown in Figure 20.



21. Carefully disconnect two (2) connectors from the back of the ACU, as shown in Figure 21.



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 11 of 17 Published: June 2019



RC-19-84-01

MODEL: 2018 Karma Revero DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)

22. Use a camera to take a clear photograph of the serial number on the label for the original ACU, as well as the label on the replacement ACU (Fig. 22).


NOTE:

- These images $\underline{\text{MUST}}$ be attached to the warranty claim, the TSS case, and retained with the repair order.
- The serial number for the part being removed, and the serial number for the part being installed, <u>MUST</u> be recorded and included with the TSS case.
- 23. Original Airbag Control Units (ACU), being returned to Karma for disposal, **MUST** have the word "**RECALL**" written on them for identification purposes, as shown in Figure 23.


⚠ NOTICE!

<u>ALL</u> original Airbag Control Units (ACU) <u>MUST</u> be returned to Karma for proper disposal.

- 24. Destroy the original Airbag Control Unit (ACU) by drilling through the body of the ACU, as shown in Figure 24. **NOTE: Do NOT drill through the serial number on the Airbag Control Unit (ACU).**
- 25. Prior to shipping the original ACU to Karma for disposal, please send an email to parts@ karmaautomotive.com to request a return shipping label.







Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 12 of 17 Published: June 2019



RC-19-84-01

MODEL: 2018 Karma Revero

DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)

A CAUTION!

To avoid inadvertent airbag system deployment, Do <u>NOT</u> reconnect the 12V system until the ACU is firmly secured in place on the mounting location.


26. Install the replacement Airbag Control Unit (ACU) (**P/N C131190101004**), by reversing the removal steps (Fig. 25).

Tightening Torque: 8Nm (±1.2Nm)

△ NOTICE!

After tightening each screw to specification, mark each screw using a paint marker.

- 27. Reinstall all removed components by reversing the order of removal.
- 28. Re-connect the 12V disconnect and install Fuse #10 back into the fuse block.



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 13 of 17 Published: June 2019



RC-19-84-01


MODEL: 2018 Karma Revero

DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)

29. Use KarmaSync to scan for DTCs and verify that fault code **B1100** is present in the system (Fig. 25).



30. After checking for DTCs, return to the homescreen and click on **Service Procedures** (Fig. 26).



31. Next, click on **Enable ASM Normal Mode** (Fig. 27).



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 14 of 17 Published: June 2019



RC-19-84-01


MODEL: 2018 Karma Revero

DATE: June 2019


Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)

32. Once in the system Enable ASM Normal Mode screen, click on **Enable Normal Mode** (Fig. 28).



33. If the process is successful, the system will report "Enabling Normal Mode was Successful" (Fig. 29). NOTE: If the operation fails, please update the TSS case with the details and wait for instructions.



34. Clear all DTCs from the system. Then, read DTCs once again to verify B1100 is no longer present in the system.

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 15 of 17 Published: June 2019



RC-19-84-01

MODEL: 2018 Karma Revero

DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)

△ NOTICE!

Clean the shock tower area, thoroughly, to promote proper campaign completion label adhesion.


- 35. Fill out and adhere the recall campaign completion label (Fig. 30) to the passenger side shock tower, as shown in Figure 31. This will serve as a clear indication that the recall has been performed and is **REQUIRED** to ensure compliance with the Airbag Control Unit (ACU) Safety Recall Campaign.
- 36. Prior to shipping back the original ACU to Karma for disposal, please send an email to parts@karmaautomotive.com to request a return shipping label.

△ NOTICE!

All Original Airbag Control Units (ACU) <u>MUST</u> be returned to Karma for proper disposal.

37. Perform Electronic Parking Brake (EPB) Calibration Procedure.

Fig.	30
	KARMA AUTOMOTIVE, LLC
	Campaign No.: Description: Retailer Code://
	For questions, please contact Client Services at 1-855-565-2762 C149950001100



Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 16 of 17 Published: June 2019



RC-19-84-01

MODEL: 2018 Karma Revero

DATE: June 2019

Released-June 2019

TITLE: Remedy, Replacement Airbag Control Unit (ACU)

PARTS REQUIRED:

PART NUMBER	DESCRIPTION	QUANTITY
C131190101004	Airbag Control Unit (ACU)	1

SHOP SUPPLIES:

	DESCRIPTION	
N/A		

SPECIAL TOOLS:

DESCRIPTION
N/A

CAUSAL PART:

PART NUMBER	DESCRIPTION
C131190101003	Airbag Control Unit (ACU)

LABOR CODES:

CODE	DESCRIPTION	TIME	DEFECT CODE
RC-00-00-08	Airbag Module Replacement	2.0	84-25-01-17

SUBLET:

CODE	DESCRIPTION	AMOUNT
N/A		

Karma Automotive Bulletins and service documents are intended for use by experienced and trained Technicians. If you lack the skills, tools, equipment and a suitable workshop for any procedure described in this document, we suggest you leave such repairs to a Karma retailer and service provider. See your service provider for advice on whether your vehicle may benefit from the information contained within this document. The information contained in the Karma Bulletin is accurate at the date of publication. However, Karma Automotive regularly updates technical information. Please check with your Karma Automotive Retailer and Karma Automotive service provider that the bulletin you intend to use contains the latest available information.

Page 17 of 17 Published: June 2019