VOLVO CAR SERVICE AND PARTS BUSINESS



Technical Journal

TITLE: Water intrusion from sealing to climate unit in plenum area

REF NO:ISSUING DEPARTMENT:TJ 32040.2.1Technical Service			ARKET: s and Canada
3 US 7	PARTNER: 7510 Volvo Car USA	ISSUE DATE: 2019-05-14	STATUS DATE: 2019-05-20
FUNC GROUP:FUNC DESC:8700Air conditioning unit		Page ⁻	1 of 22

"Right first time in Time"

Attachment

File Name	File Size
TJI-497457-2_1_2_en-US.pdf	4.2124 MB
TJI-497457-3_1_2_en-US.pdf	4.5598 MB

Vehicle Type

Туре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2017-2017		0000350-0009837	201617-201642
256							2016-2017		0000561-0144278	201505-201642

CSC Customer Symptom Codes

Code	Description
R7	Body frame/Other water leaks (sealing issues only)
A2	Climate control system/Unusual odor

VST Operation Number

VST Operation Number	Description
99400-2	General reimbursement acc. to TJ/QB
36050-2	Calibrating/Identifying with VIDA
97174-2	Air intake housing, adjust acc. to TJ32040

Produced in the USA and available as an electronic document. Hard copy documents are printed in USA on recycled paper containing a minimum of 50% wastepaper and 10% post-consumer waste. © 2019 VOLVO CAR USA, LLC

Technical Journal 32040.2.1



DTC Diagnostic Trouble Codes

Rows beginning with * are modified Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

*Title edited to improve search function

Water seepage from sealing to Climate unit in plenum area.

SERVICE:

Add new sealing on the HWAS box (Humidity Water Air Separator) and secure assembly of the box according to attached instruction.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8700.

To view TJ attachment continue to next page. This TJ has two attachments.

VOLVO	Volvo Car Customer Service	TJ Instruction VC	C-497457-2
Title	Air inlet housing	Page	1 (10)
Action	Adjustment	Operation number:	99400-2
			97174-2
			36050-2

Issue	Date	Reason
1	2016-10	First issue

Affected vehicles

ſ

Model year	Model
2016, 2017	XC90 (16-)

		Materials	
Materials	Qty.	Part No.	Notes
Isopropanol	0.02	1161721	CLEANING;
Sealing	1.0	31694105	SEAL - LHD / RHD;



Color symbols



Note! This colour chart displays (in colour print and electronic version) the importance of the different colours used in the images of the method steps.

- 1. Used for focused component, the component with which you will do something.
- 2. Used as extra colors when you need to show or differentiate additional parts.
- 3 . Used for attachments that are to be removed/installed. May be screws, clips, connectors, etc.
- 4 . Used when the component is not fully removed from the vehicle but only hung to the side.
- 5 . Used for standard tools and special tools.
- 6 . Used as background color for vehicle components.

Page 3 (10)

Check

Applies to the passenger side

Note! Orientation view



	Remove the screws.
25	

Page 4 (10)





Note! Check for moisture in the area indicated.

Reach with your hand behind the fan housing and check for moisture between the insulating mat foam and the body wall.

If no faults are detected, to install, reverse the removal procedure.

All vehicles

Removal

Remove the cowl panel cover, refer to: Removal, replacement and installation 8 - Body and interior 82 - Bonnet (Hood), front end, wings, door sill 823 - radiator grille

TJ Instruction VCC-497457-2

Set the vehicle to Active mode, described in user mode , refer to: General Information 3 - Electrical system 30 - General 300 - general

Activate service position according to: Diagnostics / Components / Control modules/ Climate Control Module (CCM) / Diagnostic sequences / Service position of damper motors

Set the vehicle to Inactive mode, described in user mode, refer to: General Information 3 - Electrical system 30 - General 300 - general



TJ Instruction VCC-497457-2

Page 6 (10)



Caution! Make sure that the flaps have reached service position (closed).

Check with your hand that the flaps have closed. If not, run the script for Service position. Do not force the flaps closed by hand!



Remove the nuts. Remove the part carefully Remove the marked part.



Cleaning



(a) (b) (c) (a)	Clean the marked area.
Es On Art	

Adjustment





Right-hand drive vehicles





Note! Make sure that the seal is correctly located.

Make sure to place the joint where indicated in the graphic.

Page 10 (10)

All vehicles

Installation



Caution! Make sure that the component is positioned correctly.



Note! Make sure to follow the sequence indicated.

Install the nuts

Torque:

Air inlet housing, to Body, 3 Nm

To install, reverse the removal procedure.

VOLVO	Volvo Car Customer Service	TJ Instruction VC	C-497457-3
Title	Air inlet housing	Page	1(10)
Action	Adjustment	Operation number:	36050-2
			97174-2
			99400-2

Issue	Date	Reason
1	2016-10	First issue

Affected vehicles

٢

Model year	Model	
2017	S90 (17-)	

Materials						
Materials	Qty.	Part No.	Notes			
Isopropanol	0.02	1161721	CLEANING;			
Sealing	1.0	31694118	SEAL - LHD / RHD;			



Color symbols



Note! This colour chart displays (in colour print and electronic version) the importance of the different colours used in the images of the method steps.

- 1. Used for focused component, the component with which you will do something.
- 2. Used as extra colors when you need to show or differentiate additional parts.
- 3 . Used for attachments that are to be removed/installed. May be screws, clips, connectors, etc.
- 4 . Used when the component is not fully removed from the vehicle but only hung to the side.
- 5 . Used for standard tools and special tools.
- 6 . Used as background color for vehicle components.

Check

Applies to the passenger side



Note! Orientation view	







Note! Check for moisture in the area indicated.

Reach with your hand behind the fan housing and check for moisture between the insulating mat foam and the body wall.

If no faults are detected, to install, reverse the removal procedure.

All vehicles

Removal

Remove the cowl panel cover, refer to: Removal, replacement and installation 8 - Body and interior 82 - Bonnet (Hood), front end, wings, door sill 823 - radiator grille

TJ Instruction VCC-497457-3

Set the vehicle to Active mode, described in user mode , refer to: General Information 3 - Electrical system 30 - General 300 - general

Activate service position according to: Diagnostics / Components / Control modules/ Climate Control Module (CCM) / Diagnostic sequences / Service position of damper motors

Set the vehicle to Inactive mode, described in user mode, refer to: General Information 3 - Electrical system 30 - General 300 - general



TJ Instruction VCC-497457-3

Page 6 (10)



Caution! Make sure that the flaps have reached service position (closed).

Check with your hand that the flaps have closed. If not, run the script for Service position. Do not force the flaps closed by hand!



Remove the nuts. Remove the part carefully Remove the marked part.



Cleaning



<u> </u>	Clean the marked area.

Adjustment

Left hand drive vehicles





Right-hand drive vehicles





Page 10 (10)

All vehicles

Installation



Caution! Make sure that the component is positioned correctly.



Note! Make sure to follow the sequence indicated.

Install the nuts

Torque:

Air inlet housing, to Body, 3 Nm

To install, reverse the removal procedure.