

Service Bulletin

Bulletin No.: 18-NA-221

Date: May, 2019

TECHNICAL

Subject: Circular Image Distortion in Circle Icons and Buick Tri-Shield Start-Up Screen

Attention: This Bulletin replaces PIC6335B. Please discard PIC6335B.

Brand:	Model:	Model Year:		Build Date:		Engine:	Transmission:
		from	to	from	to	Engine.	Transmission.
	Enclave	2018	2018	April 2, 2018	June 4, 2018		
Buick	LaCrosse	2018	2018	April 10, 2018	End of Production		
	LaCrosse	2019	2019	June 8, 2018	September 24, 2018		

Involved Region or Country	North America and N.A. Export Regions
Additional Options (RPOs)	Equipped with Infotainment System RPOs IO5, IO6

l	Some customers may comment on image distortion on any of the screens as shown in
ı	the examples below:



5091330

Condition

· Circular image distortion, Including the Buick tri-shield boot-up screen



5096158

Video image distortion

Some customers may also comment that the concern was not apparent until being operated in high ambient temperatures.

Cause

This condition may be caused by a software anomaly in the internal radio control (also known as ICS – Integrated Center Stack).

Correction

If this concern is experienced, compare the radio control assembly (ICS) calibration/software part numbers to those in TIS2Web to determine if any updated radio control assembly (ICS) programming updates are available.

Important: If no updates are present, this bulletin does not apply.

Service Procedure

Note: Stable battery voltage is critical during programming. Any fluctuation, spiking, over voltage or loss of voltage will interrupt programming. Install a GM Authorized Programming Support Tool to maintain system voltage. Refer to www.gmdesolutions.com for further information. If not available, connect a fully charged 12 V jumper or booster pack disconnected from the AC voltage supply. DO NOT connect a battery charger.

If radio control assembly (ICS) updates are available, program the radio control assembly by following the Radio Control Programming and Setup procedure in SI, making sure to complete all required programming events outlined.

Parts Information

No parts are required for this repair.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810325	Radio Control Reprogramming with SPS	Use Published Labor Operation Time

Version	2	
Modified	Released July 09, 2018	
	May 20, 2019 – Added the 2018-2019 Buick LaCrosse Model with Build Dates and updated the Stable Battery voltage during reprogramming statement.	

Additional Keywords: camera