



**Countries:** CANADA, UNITED STATES, MEXICO  
**Availability:** ISIS, Bus ISIS, FleetISIS, IsSIR  
**Major System:** STEERING SYSTEM  
**Current Language:** English  
**Other Languages:** NONE  
**Viewed:** 224

**Document ID:** IK0500061  
**Revision:** 0  
**Created:** 5/23/2019  
**Last Modified:** 6/5/2019  
**Author:** William Knoth

[Less Info](#)

Hide Details

Coding Information

<b>Copy Link</b> 	<b>Copy Relative Link</b> 	<b>Bookmark</b>  <a href="#">View My Bookmarks</a>	<b>Add to Favorites</b> 	<b>Print</b> 	<b>Provide Feedback</b> 	<b>Helpful</b>  0	<b>Not Helpful</b>  0
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	-------------------------	-----------------------------

**Title:** CE Bus Steering Won't Return to Center

**Applies To:** CE Bus w/ Tilt Columns, ESP, and Steering Switch Controls

## CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

05/30/2019 - Initial Article Release

## DESCRIPTION

This document will guide the user through diagnosing steering wheels not returning on IC CE Buses.

This document only applies to CE buses with the following feature codes:

- Tilt Column: **0005708** (Column part number 4095815C91 (Bendix) or 4110141C91 (Wabco))
- ABS with ESP: **0004AZS** (Bendix air system) or **0004JNX** (Wabco hyd. system)
- Steering wheel Switch: **0047DNK** or **0047DNU** or **0047DWC**

## SYMPTOM(s)

**Diagnostic Trouble Code(s) & Dashboard Indicator Light(s):**

There are no fault codes associated with this failure mode.

**Customer Observations or Concerns:**

The customer will notice that the vehicle will have poor return-ability, or the steering wheel may not return to "on center" after a turn, or may only return slightly.

**Note:** Return-ability definition - The feel and predictability of the steering system's center return. Steering should return towards "on center" smoothly and quickly without any binding.

## SPECIAL TOOL(s) / SOFTWARE

Tool Description	Tool Number	Comments	Instructions
Steering Wheel Puller	05-252-01		<a href="#">TL2900050</a>

## **SERVICE PARTS INFORMATION**

Kit Description	Part Number	Quantity Required	Notes
Currently there are no parts for this repair			

## **DIAGNOSTIC STEP(s)**

**WARNING:**

Always wear safe eye protection when performing vehicle maintenance. Failure to do so may result in personal injury and / or death.

**WARNING:**

Park vehicle on a hard, flat surface, turn the engine off, set the parking brake, and block the wheels to prevent the vehicle from moving in either direction. Failure to do so may result in property damage, personal injury, and / or death.

**CAUTION:**


The return-ability procedure should be performed on a flat paved surface where greater than a full lock turn can be performed safely.

**Possible Causes of low return-ability:**


- Low Steering Axle Caster
- Binding Kingpins
- Binding Draglink Ends
- Binding Tie Rod Ends
- Binding Steering Gear
- Binding Steering Shaft U-joints/Slip Joint
- Binding Steering Column

Step	Action	Decision
1	<p><b>DIAGNOSTIC:</b></p> <p><b>Determine the vehicles returnability of the steering.</b></p> <p><u>This procedure should be performed on a flat paved surface where greater than a full lock turn can be performed safely.</u></p> <p>From a full stop, turn the wheel to full lock. Take hands off the steering wheel and start to accelerate gradually, the vehicle should be making a circle. Increase the vehicle speed to no more than 20mph without hands on the wheel. Repeat the test for both left and right turns.</p> <p><b>Does the steering return in both directions to within 180 degrees or 1/2 turn of straight before the bus completes two full circles with smooth and predictable steering movement?</b></p>	<p><b>Yes.</b> No additional actions are needed</p> <hr/> <p><b>No.</b> Proceed to step 2.</p>

Step	Action	Decision
2	<p><b>DIAGNOSTIC:</b></p> <p><b>Inspect for clockspring to steering wheel interference.</b></p> <p>Remove the steering wheel and remove the clockspring.</p> <p>Without reinstalling the clockspring, install the steering wheel, torque the steering wheel nut to 55-60ft-lbs.</p> <p>With the clockspring removed repeat the return-ability test in step 1.</p> <p><b>Does the steering return in both directions to within 180 degrees or 1/2 turn of straight before the bus completes two full circles with smooth and predictable steering movement?</b></p>	<p><b>Yes.</b> Open a case file for repair instruction</p> <hr/> <p><b>No.</b> Reinstall the clockspring. Check alignment, then diagnose potential binding in the steering gear, kingpins, draglink/tie rod ends, or steering shaft.</p>



**Figure 1: Steering column cut-a-way view**






Figure 2: Steering column and steering wheel with covers removed for visual

**REPAIR STEP(s)**

**WARNING:**

Park vehicle on a hard, flat surface, turn the engine off, set the parking brake, and block the wheels to prevent the vehicle from moving in either direction. Failure to do so may result in property damage, personal injury, and / or death.

**WARNING:**

Always wear safe eye protection when performing vehicle maintenance. Failure to do so may result in personal injury and / or death.

**WARNING:**

If the vehicle must be raised, do not work under the vehicle supported only by jacks. Jacks can slip or fall over, potentially resulting in property damage, personal injury, and / or death.

Step 1. Create a case file with Navistar Tech Support for further instructions.

---

## **WARRANTY INFORMATION**

### **Warranty Claim Coding:**

Refer to the [Warranty Coding Manual](#) for Group and Noun Codes.


### **Standard Repair Time(s):**

Refer to the [SRT Manual](#) for Repair Times

---

## **OTHER RESOURCES**

[Master Service Information Site](#)

 Hide Details	<b>Feedback Information</b>
	Viewed: 223 Helpful: 0 Not Helpful: 0
No Feedback Found	

---

Copyright © 2019 Navistar, Inc.