# News Channel Update |

# Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers, Sales Managers,	FROM: Gregory Gunther, Department Manager, Vehicle Compliance and
Service Managers, Parts Managers	Analysis, Engineering Services
RE: Service Campaign Launch Notification	
Apply Preservation Agent to Jack Support Points	DATE: May 3, 2019
MY19 177 (A-Class)	

#### **IMPORTANT SERVICE CAMPAIGN INFORMATION**

Please see the attached documents related to the campaign listed above.



## Vehicle Compliance & Analysis

<b>Service Campaign Launch Notification</b>		May 3, 2019			
Campaign No. :	Campaign Desc. :	Apply Preservation Agent			
2019040015	19P6391001	(Jack Support Points)			
This is to notify you of a Service Cam	paign <b>LAUNCH</b> for certain Model Year be flagged in VMI as "OPEN	("MY") 2019 A-Class ( 177 platform) vehicles. Affected VINs will on May 3, 2019.			
Background					
Issue	Model Year ("MY") 2019 A-Cla applied to the jack support po to corrosion over time.				
What We're Doing		MBUSA will conduct a Service Campaign. An authorized Mercedes-Benz dealer will check the jack support points and apply a preservation agent if necessary.			
Parts	Parts are available and may	Parts are available and may be ordered as necessary.			
	Vehicles Aff	ected			
Vehicle Model Year(s)	lel Year(s) 2019				
Vehicle Model	A-Class	A-Class			
	Vehicle Popu	lations			
Total Population	·				
Next Steps/Notes					
AOMS	This campaign may genera	te questions from your dealers.			
While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction.  Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.					



Service Campaign Bulletin

Service Campaign Bulletin

## **Service Campaign Bulletin**



Campaign No. 2019040015, May 2019

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model A-Class (177 platform)

Model Year 2019

Apply wax as preservation agent to jack support points

Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2019 A-Class vehicles (177 platform), a preservation agent may not have been applied to the jack support points in accordance with production specifications, which could lead to corrosion over time.

Prior to performing this Service Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Service Campaign bulletin and follow the repair procedure exactly as described.

Approximately 696 vehicles are affected.

Order No. P-SC-2019040015

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

### **Procedure**

- 1. Drive vehicle onto drive-on lifting platform.
  - 1 The work can also be performed above a pit.
- 2. Remove jack support point grommets (4 pieces).
  - Remove the locking plug with a flat tip screwdriver





Figure 1

Figure 2 example of correct wax application

- 3. Rework body shell holes with wax
  - Use a brush.
- 4. Assemble in reverse order.

## **Primary Parts Information**

Qty.	Part Name	Part Number	Estimated Replacement Rate
.05*	Cavity sealing wax	A 000 986 72 70 10	100%

<sup>\*</sup>Use 1 packaging unit for approx. 20 vehicles

### **Warranty Information**

**Operation:** Apply wax as preservation agent to jack support points(02-2988)

Damage Code	Operation Number	Labor Time (hrs.)
63 910 01	02-2988	0.4

Includes: Remove jack support points

i Note

Operation Number labor times are subject to change.