

NUMBER: 08-047-19

GROUP: 08 - Electrical

DATE: May 11, 2019

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Service Bulletin 08-076-18, dated May 26, 2018, which should be removed from your files. All revisions are highlighted with **asterisks** and include an updated build date, markets, sales code, a software update, Diagnostic Trouble Codes (DTCs) and LOP.

SUBJECT:

Flash: Parktronic System (PTS) Module Updates

OVERVIEW:

This bulletin involves reprogramming the PTS module with the latest available software.

MODELS:

2019 (DT)

RAM 1500 Pickup

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA, EMEA, **APAC and LATAM.**

NOTE: This bulletin applies to vehicles built on or before **April 11, 2019 (MDH 0411XX)** equipped with Parksense FT/RR Park Assist W/Stop (Sales Codes XH4) **or Parallel & Perp Park Assist W/Stop (Sales Codes XH5).**

SYMPTOM/CONDITION:

**Customers may experience an Electronic Vehicle Information Center (EVIC) message. These DTCs may be setting erroneously and this software enhancement will remove these DTCs. Upon further investigation the technician may find that one or more of the following DTCs have been set:

- B128E-25 PTS Sensor 1-Signal Shape/Waveform Failure.
- B128F-25 PTS Sensor 2-Signal Shape/Waveform Failure.
- B1290-25 PTS Sensor 3-Signal Shape/Waveform Failure.
- B1291-25 PTS Sensor 4-Signal Shape/Waveform Failure.
- B1292-25 PTS Sensor 5-Signal Shape/Waveform Failure.
- B1293-25 PTS Sensor 6-Signal Shape/Waveform Failure.
- B1295-25 PTS Sensor 8-Signal Shape/Waveform Failure.
- B1296-25 PTS Sensor 9-Signal Shape/Waveform Failure.
- B1297-25 PTS Sensor 10-Signal Shape/Waveform Failure.
- B1298-25 PTS Sensor 11-Signal Shape/Waveform Failure.
- B1299-25 PTS Sensor 12-Signal Shape/Waveform Failure.**

Customers may experience the following:

 When backing up, the park assist feature will apply the brakes when no object is behind the vehicle.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the one listed are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above or if the technician finds the DTC, perform the Repair Procedure.

REPAIR PROCEDURE:

NOTE: Install a battery charger to ensure battery voltage does not drop below 13.2 volts. Do not allow the charging voltage to climb above 13.5 volts during the flash process.

NOTE: If this flash process is interrupted/aborted, the flash should be restarted.

- 1. Reprogram the PTS module with the latest software. Detailed instructions for flashing control modules using the wiTECH Diagnostic Application are available by selecting the application's "HELP" tab.
- 2. Clear all DTCs that may have been set in any module due to reprogramming. The wiTECH application will automatically present all DTCs after the flash and allow them to be cleared.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
18-20-05-9J	Module, Parktronic System (PTS) - Reprogram (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.

NOTE: The expected completion time for the flash download portion of this procedure is approximately 3 minute. Actual flash download times may be affected by vehicle connection and network capabilities.

FAILURE CODE:

The dealer must use failure code CC with this Service Bulletin.

- If the customer's concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C's (customer's concern, cause and correction) must be provided for processing Service Bulletin flash/reprogramming conditions.

CC	Customer Concern