

NUMBER: 23-017-19

GROUP: 23 - Body

DATE: May 23, 2019

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Rear Seat Back Squeak

OVERVIEW:

This bulletin involves lubricating the plastic overmold area on both rear seat latches.

MODELS:

2020 (JT)

Jeep Gladiator

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA.

NOTE: This bulletin applies to vehicles built on or after April 01, 2019 (MDH 0401XX) and on or before May 06, 2019 (MDH 0506XX).

SYMPTOM/CONDITION:

Customers may experience the following:

• While driving a squeak can be heard coming from one or both rear seat latches.

DIAGNOSIS:

If the customer describes the symptom/condition listed above, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1 (AR)	NPN	Door-Ease Solid Stick Lubricant or Equivelant

NOTE: Door-Ease stick lubricant is a shop supply and is not reimbursable. Please review article KB0023465 for information pertaining to shop supply reimbursement policy.

23-017-19 -2-

REPAIR PROCEDURE:

- 1. Fold both rear seat backs down.
- 2. Apply solid stick lubricant to your finger or a cotton swap applicator.
- 3. Wipe the lubricant on the C-shaped plastic pieces of the latch frame (not the moving parts) (Fig. 1) .




Fig. 1
Lubrication Points

1 - Plastic Piece Locations

4. Wipe the lubricant into the plastic around latch with a clean paper towel (Fig. 2) .



Fig. 2
Wiping Lubricant On Plastic

5. Repeat Steps 2-4 on other side seat back.

-3- 23-017-19

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-41-60-92	Latch, Folding Seat Back - Lubricate Rear Driver and Passenger Sides (1 - Semi-Skilled)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
I ——	