

L73X-
A.05.19

To: Official After-Sales Network
Subject: Installation of air ducts on the floor panel
Date: 29 Friday 2019
Pages 4



Campaign Code:
L73X-A.05.19

Campaign Description:
Installation of 2 air ducts on the floor panel

Model:
Aventador

Model Year:

MY19

Special or limited editions:
SV J

Markets:
All

VIN Identification:

From VIN KLA07903 to VIN KLA08461

Important: before proceeding with the repair, connect to the warranty portal and use VIN Info to check that:

- The vehicle is actually affected by the instructions given in this bulletin; some vehicles may not be, even when their VIN is included.
- Procedures are identified by a letter (e.g. A, B or C....etc., whose differences will be explained later in this bulletin); make sure that the spare parts corresponding to the assigned procedure are used.

Example

The screenshot shows a web interface for VIN information. At the top, there are fields for 'VIN' (17 DIGITS VIN), 'MODEL NAME', 'Start Warranty' (DD/MM/YYYY), and 'End Warranty' (DD/MM/YYYY). Below this is a section titled 'Outstanding Campaigns' with a table. The table has columns: 'Code', 'Type', 'Description', 'Bulletin', and 'Proc.'. A row is visible with 'LXX-A.XX.XX' in the Code column, 'CAMPAIGN NAME' in the Description column, and 'B' in the Proc. column. The 'Proc.' column is circled in red. At the bottom, there is a field for 'Next service planned at date'.



NOTE:

Procedure A will be available only when the instructions

require a preliminary check to be performed to determine whether or not the vehicle actually needs updating.

Network information notice:

As a result of ongoing product monitoring, Automobili Lamborghini Spa is asking you to install two air ducts on the floor panel in order to improve the cooling of the rear axle shafts.

Solution for the network:

Update the vehicle, following the instructions given in this bulletin.

Replacement parts:

Order the following codes required for the specified operation:

- Operation B - Installation of 2 air ducts on the floor panel.

P/N:	Description	Q
470801047	The kit contains: - Air intake 470825369; Quantity: 1 - Air intake 470825487; Quantity: 1 - Rivet: 470807153; Quantity: 4	1

Management of replaced parts.

Store the parts removed from the vehicle in a suitable manner, marked with their barcode for identification during visits by the competent Area Manager.

Labor

- Operation B: 0.4 hours

Bulletins superseded.

None.

Warranty instructions.

To request reimbursement for the corrective action performed, access the Warranties section of the Lamborghini HUB and follow the "Campaigns" entry instructions in the W.Claim manual which can be downloaded from the Portal.

Select the required campaign and proceed with entry, carefully reading the options present in the alert displayed by the system (see example) and select the option performed on the vehicle.

Header

CC

A-Test 1

B-Test 2

C-Test 3

Problem

A-Test 1

Cost Code

50 Service Campaign

Depending on the option performed, the reimbursement will be structured in the following manner:

- OPTION B - Installation of 2 air ducts on the floor panel.

Labor: 0.4 hours
spare parts: 470801047



WARNING!

Attach all documents generated during the work carried out as evidence of the work itself, for instance workshop orders, diagnostic protocols etc. If one or more of these is missing it may lead to a rejected reimbursement request.

Fill out the Service and Recall Campaign section in the warranty booklet, which is shown in the figure below.

Automobili Lamborghini S.p.A. **Company service assistance e campagne di richiamo / Service und Rückrufaktion / Service and Recall Campaign** **Service et campagne de rappel / Campaña de Servicio y Llamada a Taller**

Service/Service Servizio/Servizio Servicio	Richiamo/Recall Rückrufaktion/ Llamada a Taller	☐	☐
Numero/Number Número/Número Número		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐

Seguete le Istruzioni / Ausführen von der Vertriebsgesellschaft / Done by the Dealer
 (Effectuez par le concessionnaire / Efectúenlo por el Concesionario)

Service/Service Servizio/Servizio Servicio	Richiamo/Recall Rückrufaktion/ Llamada a Taller	☐	☐
Numero/Number Número/Número Número		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐

Seguete le Istruzioni / Ausführen von der Vertriebsgesellschaft / Done by the Dealer
 (Effectuez par le concessionnaire / Efectúenlo por el Concesionario)

Printa / Utskrift / Signature / Signature / Firma

Service/Service Servizio/Servizio Servicio	Richiamo/Recall Rückrufaktion/ Llamada a Taller	☐	☐
Numero/Number Número/Número Número		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐

Seguete le Istruzioni / Ausführen von der Vertriebsgesellschaft / Done by the Dealer
 (Effectuez par le concessionnaire / Efectúenlo por el Concesionario)

Printa / Utskrift / Signature / Signature / Firma

Service/Service Servizio/Servizio Servicio	Richiamo/Recall Rückrufaktion/ Llamada a Taller	☐	☐
Numero/Number Número/Número Número		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐
		☐	☐

Seguete le Istruzioni / Ausführen von der Vertriebsgesellschaft / Done by the Dealer
 (Effectuez par le concessionnaire / Efectúenlo por el Concesionario)

Tools/Materials required

Code	Description.	Q



N.B.^(*)

All ODIS technical documentation can be viewed on the Lamborghini web portal, in the corresponding ODIS section.

Preliminary operations

1. To install the air ducts, it is necessary to remove the Rear Floor Panel.

To perform this operation, follow the instructions given in the workshop manual at the following paths:

08 Body/25 Vehicle floors and heat-proof panels/Rear floor panel/Disassembly/Assembly

Procedure




Equipment


- VAS 6759 riveter or equivalent tool.
2. Position the air intake near the opening on the panel and the hole.



3. Position the rivet and secure it with the riveter.





4. Position the air intake near the 3 holes.





5. Position the 3 rivets and secure them with the riveter.
6. Installation completed:



Reinstallation

7. Reinstall the floor panel following the removal procedure in reverse order.



IMPORTANT:

The documents which must be provided with the warranty request are:

- *Produced Repair Order*
- *Saved Diagnostic Protocol*

Failure to follow these procedures could lead to the request being rejected.