


**TECHNICAL
INSTRUCTIONS FOR
LIMITED SERVICE CAMPAIGN GLD
SAFETY CONNECT SYSTEM
CERTAIN 2015 MY GS 350, LS 460, RC350
AND
CERTAIN 2016 MY GX 460, IS 200t/300/350, NX 200t**

The repair quality of covered vehicles is extremely important to Lexus. All dealership technicians performing this repair are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this repair are required to currently hold at least one of the following certification levels:

- Senior Technician
- Master Technician
- Diagnostic Specialist

It is the dealership's responsibility to select technicians with the above certification level or greater to perform this repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

I. OPERATION FLOW CHART



II. IDENTIFICATION OF AFFECTED VEHICLES

NOTE:

- A small number of vehicles involved in this campaign may have a DCM that has previously been activated. File a warranty claim to mark the vehicle complete.
- Always check the TIS Vehicle Inquiry System to confirm the VIN is covered by this Limited Service Campaign, and that the campaign has not already been completed by another dealer.
- TMS warranty will not reimburse dealers for repairs conducted on vehicles that are not affected or were completed by another dealer.

III. PREPARATION

A. PARTS

No parts are required to complete this campaign

B. TOOLS & EQUIPMENT

- Techstream 2.0 / TIS Techstream / Techstream Lite (Software 11.0 or higher)
- GR8 Battery Diagnostic Station

IV. BACKGROUND

The subject vehicles are equipped with Safety Connect, which allows drivers to contact the Lexus 24/7 response center at the touch of a button. Lexus has identified that the Safety Connect System in the subject vehicles has become disabled due to an unplanned expiration of the Mobile Identification Number/Mobile Directory Number.

V. REPROGRAM THE DCM

1. CONNECT THE GR8

- Set the GR8 to Power Supply Mode to maintain 13.5 volts during ECU reprogramming
- The charger must be connected directly to the battery**



- A battery charger set to power supply mode *MUST* be used during reprogramming**
- ECU damage may occur if the correct battery charger setting is not used**


2. TURN OFF ALL ELECTRICAL ACCESSORIES

- Turn off all electrical accessories (i.e lights, audio, and climate control systems)

3. TURN IG ON

4. CHECK SAFETY CONNECT SYSTEM OPERATION

- Press the SOS button and compare the response from the lights in the SOS button to the chart below.



5. CONNECT TECHSTREAM

6. CHOOSE TELEMATICS FROM THE SYSTEM SELECTION MENU

File Function Setup TIS User Help
System Select | Stored Data |

System Selection Menu
Select desired system and then press the arrow button to access the ECU.

System Yellow = ECU status unknown.
System White = ECU communication OK.
*System White w/Asterisk = ECU not supported or not responding.

Health Check
Customize Setting
ECU Reprogramming
CAN Bus Check
TIS Function

All ECUs	Powertrain	Chassis	Body Electrical
Engine and ECT	Cruise Control	KDSS	ABS/VSC/TRAC
PPS	Air Conditioner	SRS Airbag	Main Body
D-Door Motor	P-Door Motor	RL-Door Motor	RR-Door Motor
Master Switch	D-SEAT SW	Sliding Roof	Combination Meter
Power Source Control	Occupant Detection	Remote Engine Starter	Starting Control
PM2 Gateway	Telematics		Navigation System

Tire Pressure Monitor
Back Door P/W
Driver Seat
Smart Key

This ECU controls the one to send/receive information by wireless.
Note: Telematics cannot communicate with scantool for approximately 20 seconds after IG ON

TIS Search
Print
Main Menu

Expired on April 30, 2019

7. CHOOSE THE UTILITY OPTION, AND CLICK THE NEXT BUTTON

File Function Setup TIS User Help
System Select | Stored Data | Telematics Live

Diagnostic Code:


Code	Description	Current	Pending	History	Summary
None					

Trouble Codes
Data List
Active Test
Monitor
Utility
Dial Data List

TIS Search
Print
Close


Expired on April 30, 2019

8. CLICK DCM SERVICE ON THE UTILITY MENU



9. CHOOSE ACTIVATE DCM

a) Select Activate DCM, and click next to reprogram the DCM.



10. VERIFY THE DCM IS ACTIVATED

- a) Press the SOS (Safety Connect) button and confirm the vehicle connects to the Lexus call center

11. PRINT CUSTOMER HEALTH CHECK REPORT

- a) From the Health Check Results screen select the Customer Health Check Report button (TIS will launch when button is pressed)

Customer Health Check Button

System	Monitor Status	DTC	Curr	Pend	Hist	Perf	SB	Calibration	Upd
Engine and ECT	Inc							34715100 A4701000	
Hybrid Control								896B34701800 896B54701100 896B44701400 896B44702300	Yes
Cruise Control								F152647106	2
Tire Pressure Monitor									
ABS/ESC/TRAC									
EMPS									
Occupant Detection									
Air Conditioner									
Combination Meter								838004737004 838004737004 838004737004 590C1U2A1000	
Main Body									
L Door Motor									
Smart Key									
P Door Motor									
RR Door Motor									
RL Door Motor									
Master Switch									

- b) Log in to TIS
- c) Input Vehicle Mileage and Repair Order number
- d) Check the "Performed" campaign radio button for the applicable campaigns completed during this service event
- e) Select the Report button

Diagnostic Report

Vehicle Information

Mileage: 7787

Repair Order: 77888

Our systems show the following campaigns are outstanding. Have any of these campaigns been completed? (Check for SSC door label if unsure.)

Campaign	Performed	Not Performed
E0F	<input type="checkbox"/>	<input type="checkbox"/>
90B	<input checked="" type="checkbox"/>	<input type="checkbox"/>

- f) Confirm Customer Health Check Report information is correct
- g) Print Customer Health Check Report from TIS
- h) Sign and provide to the customer

◀ VERIFY REPAIR QUALITY ▶

- Confirm the GR8 is set up properly prior to beginning the reprogramming
- Confirm the reflash completes successfully
- Confirm the Safety Connect System is operational
- Confirm there are no DTCs in the ECU

If you have any questions regarding this update, please contact your regional representative

VI. APPENDIX

A. CAMPAIGN DESIGNATION DECODER

