

Service Bulletin

Bulletin No.: 19-NA-074

Date: June, 2019

INFORMATION


Subject: Rotor Tinnerman Push Nut Removal Requirement for Accessory Wheel and Tire Installation

Brand:	Model:	Model Year:		Breakpoint:		Engino	Transmission:
		from	to	from	to	Engine:	
Chevrolet	Silverado 2500/ 3500 HD	2020	2020				
GMC	Sierra 2500/ 3500 HD						

Involved Region or Country	North America, N.A. Export Markets, Middle East and Israel			
Additional Options (RPOs)	Equipped with ACCESSORY-WHEEL - 20 X 8.5 - J - ALUMINUM - DESIGN 1, ACCESSORY-WHEEL - 20 X 8.5 - J - ALUMINUM - DESIGN 2 (RPOs SHH, SHL)			

The purpose of this bulletin is to clarify installation requirements when installing Accessory wheels on 2020 Chevrolet Silverado HD and 2020 GMC Sierra HD. These models may include tinnerman push nuts on two of the rear wheel lugs used to retain the rear brake rotor. GM Accessory wheel part numbers 84040805 and 84040806 DO NOT include a pocket on the mounting surface to fit over these nuts. Affected wheels will contain a sticker stating that these push nuts must be removed.

Note: Installtion of these wheels over Tinnerman/Push Rotor nuts may create lateral runout, inducing a vibration.



Prior to installing affected Accessory wheels, the dealer technician must remove and discard the tinnerman push nuts (1). Failure to do so may result in unintended lug nut and wheel loosening.

Once the wheel is installed, the technician should remove the sticker on the front of the wheel. The sticker should come off the wheel with little to no residue. Residual residue can be removed with soap, hot water and a cotton cloth per the wheel cleaning instructions in the wheel instruction sheet.

Page 2 June, 2019 Bulletin No.: 19-NA-074

Version	1
Modified	Released June 17, 2019