

Service Bulletin

Bulletin No.: 10-02-32-001B

Date: June, 2019

TECHNICAL

Subject: Clunk or Knock Noise When Turning (Replace Steering Gear Bushing)

Models: 2008-2017 Buick Enclave

2009–2017 Chevrolet Traverse 2007–2017 GMC Acadia Limited 2007–2010 Saturn OUTLOOK

This bulletin is being revised to add 2011-2017 model years and update the Labor Operation number. Please discard Corporate Bulletin Number 10-02-32-001A.

Condition

Some customers may comment on a clunk or knock noise when turning.

Cause

This condition may be caused by movement in a bushing on the rack and pinion.

Correction

- Remove the steering gear from the vehicle. Refer to Steering Gear Replacement in SI.
- Measure and record the distance from the casting face (cradle side) to the end of the bushing inner sleeve.
- 3. Repeat step 2 for the second mount location.

- 4. Remove the bushings from the gear using a hydraulic press.
- Install two updated bushings, which have revised mount material, to the distance recorded in step 2 and 3.
- Reinstall the steering gear. Refer to Steering Gear Replacement in SI.

Parts Information

Causal Part	Description	Part Number	Qty
Х	Bushing- Strg Gear	20908399	2

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
7421730	Steering Gear Bushing Replacement	Use the Published Labor Operations Time