



VARIOUS CHECK CONTROL (CC) MESSAGES FOR FAILURE OF DRIVER ASSISTANCE SYSTEMS

MODEL

G05 (X5 Sports Activity Vehicle)	G07 (X7 SAV)	G20 (3 Series Sedan)	G29 (Z4 Roadster)
----------------------------------	--------------	----------------------	-------------------

SITUATION

The following messages are displayed in the Check Control display:

Park Assist

- Take over vehicle control. Park Assist failed. Parking maneuver was interrupted. If this reoccurs, get it checked by your Service Partner.

and/or

Collision warning.

- You can continue driving. Collision warning fully or partially failed. No warning is given if the distance from the vehicle in front is too short. If this recurs, get it checked by your Service Partner.

and/or

Pedestrian warning.

- Pedestrian warning fully or partially failed. There is no brake intervention in case of an acute pedestrian warning. If this reoccurs, get it checked by your Service Partner.

and/or

Lateral parking aid

- Lateral parking aid failed, park yourself. Drive to your Service Partner when the opportunity arises.

AND

The following fault is stored in the fault memory of the EPS control unit: 023000 - Energy saving mode active

CAUSE

Unfavorable software of individual control units.

CORRECTION

1. Perform a vehicle test with ISTA.

If the fault code "023000 - Energy saving mode active" is stored in the EPS control unit-

- Carry out the test module „ABL-DIT-AS6100_TRAMODE_RESET" to deactivate the energy saving mode.

2. Re-test the vehicle to confirm the original situation no longer occurs.

Note: Parts replacement will not provide a solution to this situation.

WARRANTY INFORMATION

This Service Information bulletin provides technical, diagnostic and repair-related information.

Eligible and Covered Work/Repairs

When used to repair a verified defect in materials or workmanship, the repair is covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light

To submit a claim, please follow the applicable warranty policy and procedures (Labor/Part/Sublet for applicable bulk materials) that apply to the repair that was performed.

Refer to AIR for the corresponding defect code, flat rate labor operations and flat rate unit (FRU) allowances.

Diagnosis and work time (WT) labor operation codes require individual punch times and explanations on the repair order and in the claim comments section.

[Copyright ©2019 BMW of North America, Inc.]