

## **Technical Service Bulletin**

#### PSS 01 Q8 3.0TFSI Bank 2 engine misfires

01 19 23 2054182/2 August 20, 2019. Supersedes Technical Service Bulletin Group 01 number 19-09 dated March 5, 2019 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q8	2019	All	3.0TFSI

#### **Condition**

REVISION HISTORY				
Revision	Date	Purpose		
2	-	Revised header (Updated VIN break) Revised Service (Updated software released date estimate)		
1	03/05/2019	Initial publication		

This PSS only applies if all of the following conditions are met, see Figure 1 for an example:

- MIL on, MIL flashing, or misfires reported by customer.
- Misfire DTCs are stored for more than one cylinder on Bank 2.
- DTC ambient conditions show misfires occurring at or near the same timestamp.
- DTC ambient conditions show misfires occur while engine operating condition is "Leerlauf" (idle in German).
- DTC ambient conditions show misfires occur when the vehicle is at or near 0 km/h speed.
- The vehicle is NOT currently misfiring when examined in the workshop.

If all of the above criteria are not met, this PSS does not apply and the vehicle should be diagnosed using the normal GFF process.



# Technical Service Bulletin




Figure 1. Example of applicable DTC.

### **Technical Background**

Software calibration causing misfire under certain running conditions using winter blend fuel (higher vapor pressure).



## Technical Service Bulletin

### **Production Solution**

Improved software in development.

### **Service**

- 1. If customer's vehicle condition matches the conditions listed in this PSS TSB clear DTC's and test drive vehicle. If no faults return after the test drive, explain to the customer that a solution is forthcoming and currently scheduled for the late 4th quarter of 2019. No repairs are necessary at this point.
- 2. Do not replace any components for this condition since this will not resolve the customer's concern.
- 3. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> Service), or through the Technical Assistance Page in Elsa.

### Warranty

This TSB is informational only and not applicable to any Audi Warranty.

### **Additional Information**

All parts and service references provided in this TSB (2054182) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.