

GLC63 with M177LS1 - Engine Light Illuminated - P030022 Misfire

| | |
|-------------------|--|
| Topic number | LI07.61-P-069688 |
| Version | 5 |
| Function group | 07.61 ME fuel injection/ ignition system |
| Date | 07-11-2019 |
| Validity | 253 GLC63 Equipped with M177LS1 |
| Reason for change | Parts availability |
| Reason for block | |

Complaint:

Customer complains that CEL is illuminated. May also complain of rough running.

Cause:

Under investigation.

| Attachments | |
|---------------------------------------|---------------------------|
| File | Description |
| BR253_ground_points.pdf | Ground Point Locations |
| M177LS2 Intake Manifold Leak Area.jpg | Intake manifold leak area |

Remedy:

1.) Smoke test intake/exhaust and check for leaks.

- Working each bank one at a time; remove the upstream O2 sensor and install the smoke tip.
- Seal around the tip to ensure there are no leaks.
- Seal the exhaust tip outlet to the O2 sensor bung.
- Turn the smoke machine on at the maximum possible pressure.
- Look for leaks in the exhaust.
- Using very soapy water (it should create suds by itself by spraying) saturate all connections.
 - Look for signs of bubbles.
 - Move and stress the components.
 - Perform the check with engine cold and after a 5 minute run time (lukewarm).
- Working each bank one at a time, install the smoke machine tip into the intake air temperature sensor port.
- Remove the oil fill cap.
- Turn the pressure up on the smoke machine to maximum and fill the engine with smoke until it begins to come out of the oil fill port.
- Reinstall the oil fill cap.
- Look for leaks.
- Using very soapy water (it should create suds by itself by spraying) saturate all connections.
 - Look for signs of bubbles.
 - Perform the check with engine cold and after a 5 minute run time (lukewarm)
- If leaks are found, open a PTSS case and perform the following:
 - Repair the leaks as necessary.
 - Clear the mixture adaptations, clear the fault codes, and perform 2 AMG Engine Adaptation Drives (this can be found in the AMG User's Guide)
 - Pull the new injector performance data. Label this "IPDA"

XENTRY TIPS

- Compare the new injector performance data to the initial injection performance data pulled when the car first arrived.
 - The ORA and FRA values should have changed.
 - If the ORA/FRA values have not changed; stop and ask for assistance in the PTSS case.
- Then perform another 2 AMG Engine Adaptation Drives and pull the injector performance data again. Label this "IPDB"
- Upload all three injector performance data printouts to the PTSS case.
- If no leaks are found proceed to step (2)

2.) Check driver's side intake manifold for cracks near the rear (see attachments) of the engine.

- If damage is found, order a new manifold for the driver's side bank from EPC and OPEN PTSS case with pictures of damage.
- Include the following:
 - Production stamp on the damaged manifold (looks like a pair of clocks)
 - Production sticker
- If no damage is found, or repair does not remedy complaint proceed to step (3).

3.) Measure the following grounds. If any reading is above 0.5 ohm, check grounding locations (per attachments).

- ME Connector F, Pin 1 to ground
- ME Connector F, Pin 2 to ground
- ME Connector F, Pin 4 to ground
- ME Connector M, Pin 6 to ground
- ALL Coils, Pin 1 to ground
- Rework grounding locations by removing and cleaning the chassis ground point(s) of any paint or debris.
- If rework/replacement does not remedy complaint, proceed to step (4).

4.) If the check engine light returns while trying to complete step (4) open a PTSS case IMMEDIATELY and INCLUDE IN THE CASE:

1. All Data from previous steps
2. MED1775 control unit log
3. Fault codes without status filter
4. Software update check for ME and transmission control units
5. Graphical version of the fault counter per the instructions in the attachments
6. PICO compression test or manual compression test of all cylinders

| Attachments | |
|--------------------------------|----------------------------|
| File | Description |
| Hot-Cold Misfire Detection.pdf | Hot-Cold Misfire Detection |
| Fault Counter.pdf | Fault Counter Instructions |

| Symptoms |
|--|
| Power generation / Engine management / Engine running / Runs rough/shakes |
| Power generation / Engine management / Indicator lamp / Engine diagnosis / lit |

| Control unit/fault code | | |
|---|------------|--|
| Control unit | Fault code | Fault text |
| N3/10 - Motor electronics 'MED1775' for combustion engine 'M178' (ME) | P030027 | Combustion misfiring has been detected. The signal change rate is above the permissible limit value. |

XENTRY TIPS

| | | |
|---|---------|--|
| N3/10 - Motor electronics 'MED1775' for combustion engine 'M178' (ME) | P030485 | Combustion misfiring of cylinder 4 has been detected. There is a signal above the permissible limit value. |
| N3/10 - Motor electronics 'MED1775' for combustion engine 'M178' (ME) | P030185 | Combustion misfiring of cylinder 1 has been detected. There is a signal above the permissible limit value. |
| N3/10 - Motor electronics 'MED1775' for combustion engine 'M178' (ME) | P030385 | Combustion misfiring of cylinder 3 has been detected. There is a signal above the permissible limit value. |
| N3/10 - Motor electronics 'MED1775' for combustion engine 'M178' (ME) | P030685 | Combustion misfiring of cylinder 6 has been detected. There is a signal above the permissible limit value. |
| N3/10 - Motor electronics 'MED1775' for combustion engine 'M178' (ME) | P030285 | Combustion misfiring of cylinder 2 has been detected. There is a signal above the permissible limit value. |
| N3/10 - Motor electronics 'MED1775' for combustion engine 'M178' (ME) | P030785 | Combustion misfiring of cylinder 7 has been detected. There is a signal above the permissible limit value. |
| N3/10 - Motor electronics 'MED1775' for combustion engine 'M178' (ME) | P030585 | Combustion misfiring of cylinder 5 has been detected. There is a signal above the permissible limit value. |
| N3/10 - Motor electronics 'MED1775' for combustion engine 'M178' (ME) | P030022 | Combustion misfiring has been detected. The signal amplitude is greater than the maximum amplitude. |
| N3/10 - Motor electronics 'MED1775' for combustion engine 'M178' (ME) | P030885 | Combustion misfiring of cylinder 8 has been detected. There is a signal above the permissible limit value. |