Century Class Conventional Argosy Cargo Columbia 122SD and Coronado Business Class M2
> Cascadia
108SD/114SD
New Cascadia

Freightliner Service Bulletin

## **General Information**

On some Cascadia vehicles, when a request for wiper activation is made the wipers may not function. This can result from an overcurrent condition, which causes the wipers to stop functioning and immediately set fault code **SPN 522215 FMI 6**. Any additional change to the wiper request will result in the wipers operating normally.

SAM Cab software R6.4 incorporates the additional request within SAM Cab controls for the wiper, prior to generating fault code **SA 33 SPN 522215 FMI 6**. This eliminates the possibility of the wipers not running due to an invalid current above normal condition. If SAM Cab software is at R6.4, or later, and the wipers are not operating as expected, refer to the troubleshooting for fault code **SA 33 SPN 522215 FMI 6** in **Section C06.01 - Windshield Washer/Wiper** in the *Cascadia Troubleshooting Manual*.

## **SAM Cab Software Update**

- 1. Park the vehicle, shut down the engine, and apply the parking brakes. Chock the tires.
- 2. Connect the vehicle to DiagnosticLink. Make sure that DiagnosticLink is updated to the latest version, 8.09sp2. To update DiagnosticLink, select "Update" from the dropdown menu under "Tools." See Fig. 1.




Fig. 1, Updating DiagnosticLink to the Latest Version

IMPORTANT: Before performing this procedure, make sure to address any pre-existing conditions or fault codes first.

It is recommended when flashing to configure DiagnosticLink to connect only to "Default" modules, and stay in this configuration unless there is a specific need to manually connect to the Common Telematics Platform (cTP) ECU. Default modules allow DiagnosticLink to connect only to the modules that need flashing, and ignores things components the cTP or the steering angle sensor.

FLA COE FLB COE FLD Conventional Business Class FLC 112 Conventional Century Class Conventional Argosy Cargo Columbia 122SD and Coronado Business Class M2 > Cascadia 108SD/114SD New Cascadia

To make this change in DiagnosticLink:

• From the drop-down menu click "Tools", and select "Options."

Find and select the "Connection" tab.

Click the "Select Defaults" box on the right side of the tab, and click "Apply."

3. Select "Program Device." If there are any items in the section "Request Pending" downloads, they should be removed. To remove them, select the "Request Pending" list item, then press the "Remove" button. See Fig. 2.




Fig. 2, Removing Pending Requests

Once all controllers are connected, read the vehicle parameters. See Fig. 3.




Fig. 3, Reading Vehicle Parameters on DiagnosticLink

Century Class Conventional Argosy Cargo Columbia 122SD and Coronado Business Class M2 > Cascadia 108SD/114SD New Cascadia Freightliner Service Bulletin

5. Select "Program Device." There should be data to upload. Click "Connect to Server" to upload vehicle parameters to the server. See Fig. 4.




Fig. 4, Uploading Vehicle Parameters

6. Click "Add" to add a download request for the vehicle. See Fig. 5.




Fig. 5, Adding the VIN to Download Updated Server Data

7. Make sure the correct VIN and hardware is populated, then click OK. See Fig. 6.

FLA COE FLB COE FLD Conventional Business Class FLC 112 Conventional Century Class Conventional Argosy Cargo Columbia 122SD and Coronado Business Class M2 > Cascadia 108SD/114SD New Cascadia




Fig. 6, Verifying Correct VIN Hardware

8. There should be a request pending status for the VIN. Click "connect to server" to download the updated unit data. See **Fig. 7**. The server will provide any new software available on the server as well as updated parameter sets for the new software, adjusted for the parameter set that was just uploaded from the vehicle.

Century Class Conventional Argosy Cargo Columbia 122SD and Coronado Business Class M2
> Cascadia
108SD/114SD
New Cascadia

Freightliner Service Bulletin




Fig. 7, Downloading Updated Unit Data

9. Once the data has been downloaded, click "Next". See Fig. 8.




Fig. 8, Clicking Next

NOTE: "Latest" is the last service record (may be older software) and "Newest" is the most up to date software available for the installed hardware. Both will have parameter sets that have been updated relative to the upload from the vehicle.

10. Select the SAM Cab controller to program, select the VIN, and select "Newest." Click "Next." See Fig. 9.

FLA COE FLB COE FLD Conventional Business Class FLC 112 Conventional Century Class Conventional Argosy Cargo Columbia 122SD and Coronado Business Class M2 > Cascadia 108SD/114SD New Cascadia




Fig. 9, Selecting "Latest" or "Newest" Software

11. Review and verify the VIN and hardware part number. Click "Start" to program the controller. The software will be flashed and the new parameter set will be written to the controller on the vehicle. See Fig. 10.

Century Class Conventional Argosy Cargo Columbia 122SD and Coronado Business Class M2 > Cascadia 108SD/114SD New Cascadia Freightliner Service Bulletin




Fig. 10, Programming the Controller

IMPORTANT: After programming is complete, the following message may appear in DiagnosticLink: "The connected vehicle contains powertrain and Chassis devices with incompatible software versions, you will need to update these control devices using Program Device. Click here for more information." If this message is shown, continue with the next step. Otherwise, go to step 15.

12. Click on the banner message. See Fig. 11.

FLA COE FLB COE FLD Conventional Business Class FLC 112 Conventional Century Class Conventional Argosy Cargo Columbia 122SD and Coronado

Business Class M2 > Cascadia 108SD/114SD New Cascadia




Fig. 11, Clicking on the Banner Message

13. Print or take a screen shot of the incompatible ECUs. See Fig. 12.

Century Class Conventional Argosy Cargo Columbia 122SD and Coronado Business Class M2 > Cascadia 108SD/114SD New Cascadia Freightliner Service Bulletin




Fig. 12, Printing the List of Incompatible ECUs

14. Program all devices listed as incompatible from the previous step.

IMPORTANT: After a programming, some fault codes may become active and some ECUs may not auto connect. Cycling the ignition may clear the faults and reconnect the ECUs.

- 15. Cycle the ignition 3 times, waiting 30 seconds between key off and key on.
- 16. Turn the key to the ON position and connect the vehicle to DiagnosticLink.
- 17. Verify that Sam Cab SW is now R6.4 by clicking on the "Identification" page, locate "SAMCAB\_P3 Sam Cabin" and confirm that the Software Part Number is A002 448 34 58 ZGS 001, and that the Diagnostic Variant Part Number is A0004445658-002. See **Fig. 13**.

FLA COE FLB COE FLD Conventional Business Class FLC 112 Conventional Century Class Conventional Argosy Cargo Columbia 122SD and Coronado Business Class M2 > Cascadia 108SD/114SD New Cascadia




Fig. 13, SAM Cab Parameter

- 18. Turn the ignition to the OFF position, unplug DiagnosticLink, and wait one minute.
- 19. Connect DiagnosticLink, turn the key to the ON position. Clear inactive faults, and troubleshoot any active faults.
- 20. Disconnect vehicle from DiagnosticLink.

Century Class Conventional Argosy Cargo Columbia 122SD and Coronado Business Class M2 > Cascadia 108SD/114SD New Cascadia Freightliner Service Bulletin

## Warranty

This procedure is warrantable only if the described condition exists and the repair is performed within the applicable base or extended coverage warranty period. If a failure is not found, this procedure is considered preventive and warranty does not apply.

Normal warranty applies. See **Table 1** for OWL VMRS codes and labor allowance information. Enter this service bulletin number in the *Service Bulletin #* field.

OWL VMRS Codes and Labor Allowance					
Primary Failed Part	Component Code	Cause Code	SRT Code	Description	Time: Hours
Software Update, SAM Cab	003-006-016	23	32A-5021A	Software Update, SAM Cab	0.5
Each Additional Module for Compatibility		23	32A-5021B	Software Update for Compatibility	0.2

Table 1, OWL VMRS Codes and Labor Allowance

NOTE: Add the digital photo instructions only if requested by Warranty in their approval routing. Otherwise, delete the content for approval routing. Attach digital photos directly to the claim on the Attachments tab.