				Countries:	BAHAMAS, BOLIVIA, BELIZE, C COLOMBIA, COSTA RICA, DOI EL SALVADOR, TRINIDAD ANE URUGUAY, VENEZUELA, MEX PUERTO RICO, CUraçao, GUAI HONDURAS, JAMAICA, KORE/	CANADA, CHILE, TAIWAN, MINICAN REPUBLIC, ECUAD) TOBAGO, UNITED STATES ICO, ARUBA, NICARAGUA, P M, GUATEMALA, GUYANA, H A, SOUTH KOREA, PANAMA	OR, , Document ERU, ID : AITI,	IK1200478
				Availability:	ISIS, Bus ISIS, FleetISIS, IsSIR		Revision:	14
				Major System:	ENGINES		Created:	3/23/2010
Knowledge B	lase			Current Language:	English		Last Modified:	8/13/2019
				Other Languages:	Français, Español,		Author:	Allan Hertko
				Viewed:	36671			
								Less Info
Hide Details				Coding Inform	nation			
Copy Link	Copy Relative Link	Bookmark	Add to Favorites	Print	Provide Feedback	Helpful	Not Helpful	
GO		View My Bookmarks	*	+	P	2752	1483	
Title: On vehic	le DOC Cleanin	g MaxxForce®	7 Engines					

Applies To: 2007 - 2009 MaxxForce® 7,

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

08/13/2019- Changed to NED from ServiceMaxx.	i i i
08/08/2019- Responded to feedback via email and phone conversations, republished article.	<u>^</u>
01/24/2019 - Edited article coding	
11/13/2018- Responded to feedback via email, republished article.	\sim
05/02/2015 - Author updated for feedback purposes	

DESCRIPTION

A method to clean the DOC on the vehicle with NED in combination with ZTSE 6031 has been developed.

A partially plugged DOC may cause excessive Exhaust Back Pressure and cause a rise in engine oil level due to fuel dilution.

When the ECM calibration is updated the (parameter 87002) Customer Password (CPW) is restored to Calibration default (0000). You will need to acquire the CPW and program it back in when finished with the update. The only exception to this is if the ECM is updated with NETS and we have the CPW saved in our database, then the CPW will be programmed back into the ECM during a cal update. If this happens, see the note on step 11 of this article.

SYMPTOMS

- Loss of power
- Excessive regens
- Unable to regen
- Rise in oil level
- High exhaust back pressure

POSSIBLE DIAGNOSTIC TROUBLE CODES

DTC	MODULE	DESCRIPTION
2352	ECM	EBP above desired level

SERVICE PROCEDURE



To prevent unexpected movement of the vehicle and possible serious personal injury or death, park the vehicle on a flat, level surface, set the parking brake, turn the engine off and chock the wheels to prevent vehicle from moving in both directions.



To avoid personal injury from the muffler and exhaust system allow the vehicle to cool sufficiently before servicing the muffler and exhaust system.

Maintain adequate clearance between all parts of the exhaust system and all hoses, wires and lines for engine cooling, brake system, fuel system, power steering system and electrical system. Ensure that all components near the exhaust system are free of oil or other flammable debris. If the

heat from DOC cleaning accumulates to certain amount near the exhaust system, it may set nearby items on fire and result in property damage, personal injury or death.

- 1. Remove the three M10 X 50 flange bolts at the rear of the DPF.
- 2. Insert Restrictor plate torque bolts to 40 lbf-ft. (School Bus and horizontal tailpipe only) See Photo 1



^{3.} For Vertical Exhaust install Restrictor Cap as shown in Photo 2 - Tighten clamps bolts to 60 ft. lbs.

CAUTION : UPDATE! A tool modification kit for ZTSE6031 was shipped to all dealers in May 2011. ZTSE6031 should ONLY be used AFTER this modification has been completed. Additional information- https://evalue.internationaldelivers.com/service/sfnpdf/IT11-126.pdf and https://evalue.internationaldelivers.com/service/sfns/sfn1042_1.xml

1		



- 4. Disconnect both the EGDP tubes from the rubber hose at the EGDP Sensor
- 5. Install the 2 EGDP Plugs and hoses supplied with tool kit. See Photo 3



6. Move vehicle outside and away from activity.

7. Ensure Parking Brake is set.

8. Open hood

×	WARNING:	
To p	revent unexpected movement of t	he vehicle and possible serious personal injury or death, park the
vehi	cle on a flat, level surface, set the	parking brake, turn the engine off and chock the wheels to
prev	ent vehicle from moving in both d	irections.

×		
	WARNING:	
		•
Ope	n hood during on-vehicle DOC cleaning.	. This can greatly reduce the effects of heat on hoses, wiring and other
com	ponents near the exhaust system. If the	e heat from DOC cleaning accumulates to certain amount near the exhaust

system, it may set nearby items on fire and result in property damage, personal injury or death

9. Connect NED, ignition Key-On identify vehicle.

10. NED menu click on Procedures.

11. Scroll down to KOER Aftertreatment Procedures, click-on DOC Cleaning Procedure.



12. NED will now the load parameters required to run this procedure, this may take a few moments.

Note: During steps 10-11 of the procedure if the message displayed below appears there is a customer password present in this vehicle.

Diagnos	itics Test Complete	×
(į)	The DOC Cleaning Procedure is complete: DOC Clean Procedure Unable to Set	Parameters
	ОК	

You will need the customer password to move forward. Change the password (parameter 87002) to 0000, run the procedure and then program the customer password back into the engine when the procedure is complete. If the customer password is unavailable please contact tech central.

13. DTC 2352 and 1213 may set ignore these DTC codes.

14. After reading the pre-test information click "OK", See below:



15. Start engine when prompted.

16. Click <u>"OK"</u> after engine is running.

17. The cleaning procedure will now start, engine RPM will increase automatically and will return to idle automatically after the cleaning process has been completed.

Procedure will run approximately 5 minutes after EGT 1 and EGT 2 reach 800 degrees.

NOTE:	
Procedure can be aborted at any time by touching any ped	al.

18. Allow engine to remain at idle until prompted to turn engine off.

19. Please turn engine off. Press "OK" to continue.

- 20. Leave engine off and click <u>"OK"</u>.
- 21. "Turn Key On" but leave engine off when prompted.
- 22. Click "OK".
- 23. NED will now Change back the original parameters and clear the codes.

24. NED will automatically save a Snap Shot that needs to be attached to the case file.

25.Click <u>"OK"</u>.

26. The cleaning procedure has been successfully performed with the "DOC Cleaned" prompt.

27. Click <u>"OK"</u>.

- 28. Verify codes have been cleared.
- 29. NED can now be disconnected hood closed and unit moved back in building.

×	WARNING:	
Exhaust	will be very hot and care should be ta	aken to prevent injury during the following steps. Wear Heat protective gloves

- 30. Remove restrictor plate or cap
- 31. If the retrictor plate was used Inspect the gasket and reuse if possible.
- 32. Reinstall bolts, Torque bolts to 45 lbf-ft.
- 33. Remove EGDP Plug.
- 34. Reconnect EGDP hoses to tubes.

NOTE:

After Running the DOC Cleaning Procedure, fault code 1213 Remote Throttle Signal Outof Range may become active.

DTC	MODULE	DESCRIPTION
1213	ECM	Remote Throttle Signal Out-of-Range

RESOLUTION Connect with Service Maxx, set ECM parameter 75001 to 2, In Cab Operation only.

Alide Details

Feedback Information

	Viewed: 36670
	Helpful: 2752
	Not Helpful: 1483
No Feedback Found	

Copyright © 2019 Navistar, Inc.