

Preliminary Information

PIT5700 Service Front Camera Message

Models


Brand:		Model:	Model Years:	VIN:		Engine	Transmissions:
				from	to	Engine:	Transmissions.
Chevro	let	Blazer	2019	All	All	All	All

Involved Region or Country	North America			
Condition	A vehicle may be brought to the dealer with a message "Service Front Camera". Upon inspection of the vehicle it may be found that all active safety system functions including adaptive cruise control and (LKA) lane keep assist appear to work as designed. It may be noted that the LKA indicator in the DIC does not come on. There will be no DTC's stored for the FVCM systems.			
Cause	Loss of low speed communication to the K124 ASCM (Active Safety Control Module) or the B174W Front View Camera Module (FVCM)			

Correction:


Verify that both the K124 ASCM and the B174W FVCM are communicating on the low speed bus.


To confirm communication connect the data bus diagnostic tool to the vehicle, select the "detected state" tab and select "DLC terminal 1". Look through the list of communicating modules and ensure that the B174W and K124 are both on the list.



If it is found that the ASCM is not communicating on low speed inspect circuit 5060 for an open in the harness near JX300 which is located at the base of the left B pillar.

See # 1 below:





If an open is found repair the circuit following SI Serial Data Circuit Wiring Repairs.

If it is found that the B174W FVCM is not communicating on low speed, inspect X203 at the base of the A pillar for bent, loose or backed out terminals.

If both modules are communicating on low speed follow SI for diagnosis of concern.

Warranty Information

For wiring repairs covered under warranty, please refer to latest version of bulletin 10-00-89-005 for warranty information on wire/connector repairs.

Version History

Version	1
Modified	Created 8/2/19

















GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.