



Bulletin No.: PIP5671

Published date: N/A

Preliminary Information

PIP5671 Malfunction Indicator Lamp MIL Illuminated DTC P0746 And Or P0776 Set

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Malibu	2019	All	All	All	MRG

Involved Region or Country	North America
Additional Options (RPO)	None
Condition	Some customers may comment that the MIL is illuminated. Technician's may find one or more of the following DTC's set in the Transmission Control Module (TCM). P0746: Transmission Control Solenoid Valve 1 Stuck Off P0776: Transmission Control Solenoid Valve 2 Stuck Off
Cause	This condition may be caused by an internal failure in the transmission fluid pressure sensors.

Correction:

Review the GDS2 DTC Freeze Frame Data:

If the Freeze Frame data for one of the sensors reads low or zero PSI, then replace both transmission fluid pressure sensors.

Refer to SI for replacement procedure.

If both sensors indicate low or zero pressure, refer to SI for the DTC diagnostic procedure.

Service Procedure

Refer to Automatic Transmission Fluid Pressure Sensor Replacement in SI.

Important: Replace the sensors one at a time and torque bolts to specification before doing the other sensor. This will maintain the valve body to spacer plate seal.

Parts Information

The VT-40 automatic transmission Fluid Pressure Sensors (Qty 2) can be obtained from the Warranty Parts Center (WPC) using the TSP Dealer Request Form located on Global Connect<Service Department>Service Forms Application<General Information tab>TSP Dealer Request Form. Instructions for submitting are on the form. Request part (WPC840).

Warranty Information

Labor Operation	Description	Labor Time
8462540	Automatic Transmission Fluid Pressure Sensor Replacement	Used Published Labor Time

Version History

Version	1
Modified	08/16/2019 - Created



© 2019 General Motors. All Rights Reserved.