

Check Air Suspension Message Displayed With C1752 -Replace the Compressor/Motor Assembly

Service

Category Suspension

| Section | Suspension Control System | Market USA | ASE Certification |
|---------|---------------------------|------------|-------------------|
| | | | |

Applicability

| YEAR(S) | MODEL(S) | ADDITIONAL INFORMATION |
|-------------|----------|------------------------|
| 2013 - 2017 | LS460 | |

Introduction

Some 2013 – 2017 model year LS460 vehicles may exhibit a Check Air Suspension message in the instrument cluster with Diagnostic Trouble Code (DTC) C1752 (Height Control Compressor Motor Circuit Function). This condition may be caused by corrosion in the height compressor due to water intrusion through the air inlet tubes. Follow the Repair Procedure in this bulletin to address this condition.

Warranty Information

| OP CODE | DESCRIPTION | TIME | OFP | T1 | Т2 |
|---------|---------------------------------|------|-------------|----|----|
| EL1913 | R & R Height Control Compressor | 1.8 | 48914-50031 | 8B | 17 |

APPLICABLE WARRANTY

• This repair is covered under the Lexus Basic Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.

• Warranty application is limited to occurrence of the specified condition described in this bulletin.

Parts Information

| PART NUMBER | PART NAME | |
|-------------|------------------------------------|---|
| 48914-50031 | Compressor, Height Control, No. 1 | 1 |
| 48925-50080 | Filter, Height Control | 2 |
| 48962-50010 | Cushion, Height Control Tube Cover | 1 |

Check Air Suspension Message Displayed With C1752 - Replace the Compressor/Motor Assembly

Required Tools & Equipment

| REQUIRED EQUIPMENT | SUPPLIER | PART NUMBER | QTY |
|-------------------------------|---------------------|-------------|-----|
| Techstream ADVi* | | TSADVUNIT | 4 |
| Techstream 2.0 | | TS2UNIT | |
| Techstream Lite | Techstream Lite ADE | | |
| Techstream Lite (Green Cable) |] | TSLP2DLR01 | |

*Essential SST.

NOTE

- Only ONE of the Techstream units listed above is required.
- Software version 14.10.028 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.

Repair Procedure

1. Check for stored DTCs.

Is DTC C1752 (Height Control Compressor Motor Circuit Malfunction) present?

- YES Continue to step 2.
- NO This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
- 2. Replace the height control compressor.
 - A. Remove the height control compressor.

Refer to TIS, applicable model and model year Repair Manual:

- <u>2013</u> / <u>2014</u> / <u>2015</u> / <u>2016</u> / <u>2017</u> LS460: *Engine/Hybrid System – Engine Control –* "Suspension Control: Height Control Compressor: Removal"
- B. Install the NEW height control compressor.

Refer to TIS, applicable model and model year Repair Manual:

 <u>2013</u> / <u>2014</u> / <u>2015</u> / <u>2016</u> / <u>2017</u> LS460: *Engine/Hybrid System – Engine Control –* "Suspension Control: Height Control Compressor: Installation"

Check Air Suspension Message Displayed With C1752 - Replace the **Compressor/Motor Assembly**

Repair Procedure (continued)

3. Attach the height control tube cover cushion on the two NEW height control filter cases and install it to the reinforcement.

NOTE


To reduce water intrusion into the filter reinforcement, install the NEW height control filter with the height control tube cover cushion attached to both sides. The right-hand filter will be reconnected to the height control system, and the left-hand filter will be used to close the system from water intrusion from bumper reinforcement.

- A. Cut two 8 mm x 8 mm x 120 mm pieces of the height control tube cover cushion.
- B. Remove the paper backing, allowing the adhesive surface to be exposed.
- C. Attach the height control tube cover cushion.

Compress the sealer while applying the adhesive side of the sealer between the reinforcement and the filter base. (See Figure 1.)

NOTE


- Make sure the cushion is attached to the filter in the space behind the front of the filter reinforcement. (See Figure 2.)
- Secure clearance for drainage. The foam seal will be installed to the sides and top of the filter.







1

Тор







D. Repeat for the second filter.

Check Air Suspension Message Displayed With C1752 - Replace the Compressor/Motor Assembly

Repair Procedure (continued)

4. Install both filters to each side of the reinforcement.

Figure 3.

