

Newmar Corporation

PO Box 30
Nappanee, IN 46550



WHEN YOU KNOW THE DIFFERENCE.

TSB 547
Aug. 22, 2019

TECHNICAL SERVICE BULLETIN

AFFECTED MODELS

2020 New Aire, Mountain Aire, London Aire, Essex, King Aire (early production coaches only)

DESCRIPTION

Due to some ceiling light changes, dimming the lights may cause the lights to flicker.

UNITS AFFECTED

Please refer to the attached population list for affected coach production numbers and VINs.

CORRECTIVE ACTION

Count the front ceiling lights that are activated when the entry door is opened. Check to see if the coach has recliners with two overhead reading lights. Contact your Newmar Service Account Manager to obtain authorization and to order parts. Follow the attached instructions to replace the KIB boards and the specific lights.

PARTS NEEDED

Item Description	Quantity	Newmar Part #
KIB Circuit Board	1	150014
KIB Circuit Board	1	150015
KIB circuit board	1	150016
Bell Caps	2	41969
Recessed Ceiling Light with Leaf Spring Clips	2-4	150081
Reading Light	0 or 2	150078
Brown Scotchlok Connectors	2 per light	18511

FLAT RATE CODE: TSB 547

LABOR TIME: 1.0 hr for the KIB replacement boards; .1 hr for each replacement light

NOTE

Total time authorization will depend on the amount of lights requiring replacement based on the instructions. Final payment will be based on the returned parts.

IMPORTANT: Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

NOTICE: Any technical information published in this bulletin is intended for use only by a qualified, Newmar-authorized service technician. Newmar is not responsible for the misuse of this information.

Problem: Flickering ceiling lights in early-production 2020 coaches

Affected Coach Models: New Aire, Mountain Aire, London Aire, Essex, King Aire

Solution: Replace 3 KIB circuit boards and various lights (depending on configuration)

Necessary Tools

- Phillips Screwdriver
- 7/16" Nut Driver OR, 7/16" Socket with 1/4" Drive, and 1/4" Ratchet
- 7/16" Wrench
- Cordless Screw Gun with Phillip's and Square Bits


Necessary Parts

- 1 - Circuit Board (Newmar part #150014)
- 1 - Circuit Board (Newmar part #150015)
- 1 - Circuit Board (Newmar part #150016)
- 2-4 - Front Entry Door Lights with Leaf Spring Clips (Newmar part #150081)
- 2 - Reading lights (on select coaches only, Newmar part #150078)
- 2 - Bell Caps (Newmar part #41969)
- 2 - Scotch Locks (2 per light; Newmar part #18511)

Work Instructions

Removing the Old Circuit Boards

1. Turn off the battery disconnect.
2. Locate and open the KIB box (normally located in the rear closet area) by removing the three screws across from the hinges.
3. Locate the three circuit boards located in the KIB box. One is located on the door, and the other two are located on the back wall of the KIB box.
4. Mark the wire location for each board (suggestion L1- 4+ common and R1- 4+ common). You can also group the wires by putting a piece of tape around them or a zip tie. Take a picture for reference, just in case the wire markings come off.




5. Remove the old boards gently, as they must be returned undamaged for credit. Save the cover, spacers, and screws to reinstall with the new board.
6. Verify that the replacement board has the same part number (i.e.: #144771-MOD replaces #144771).



Installing the New Boards

7. Hook up the wire(s) with the ring terminals that were removed when taking off the circuit board. Using a backer wrench, tighten the nut with a nut driver or socket and ratchet.
 - o Caution: Do not over tighten the nuts, as damage to the circuit board may occur.
 - o Note: A backer wrench cannot be used on the back two boards if they are mounted before the wire(s) are connected.
8. Install the center screw, and align the other screw holes before tightening.
 - o Caution: Do not over tighten the screws, as damage to the circuit board may occur.
9. Use the plastic spacers when installing the black cover at each corner screw.
10. Install the light circuit wiring on the new circuit board just as it was when the wires were removed.
11. Repeat the process for the two remaining circuit boards.
12. Once all three circuit boards are mounted, take the orange wire at the bottom of each new board and connect them together with a bell cap. Then do the same for the black wires.



Testing the New Circuit Boards

1. Turn on the disconnect switch.
2. Test the function of all the lights to make sure that all of the wires are hooked up correctly.
3. Close the cover to the KIB box, and secure it with screws.

Replacing the Lights

1. Depending on the coach and floor plan, replace either two or four lights. The ceiling lights that require replacement are determined by checking the ceiling light operation. They are the lights that operate automatically when the entry door opens and closes.



2. Replace the two eyeball lights (on coaches equipped with the recliner options). There are likely two lights in the overhead cabinet above the recliners that are dimmable.



3. Wrap the old circuit boards in plastic. Then package and return the circuit boards and lights to Newmar.



Production #	VIN Number	Year	Brand	Type	Floor Plan	Chassis Brand	Date In Production	Date Off Production
501674	4VZVU1E94LC086325	2020	LA	DP	4543	S	12/5/2018	12/11/2018
501682	4UZFCFTG4LCLL6157	2020	LA	DP	4559	FL	2/19/2019	2/26/2019
501692	4UZFCFTG8LCLX0022	2020	LA	DP	4543	FL	5/21/2019	6/3/2019
501693	4UZFCFTG1LCLW3736	2020	LA	DP	4551	FL	5/29/2019	6/7/2019
501707	4VZVU1E93LC087546	2020	LA	DP	4543	S	6/3/2019	6/11/2019
501715	4UZFCFTG9LCLW7677	2020	LA	DP	4543	FL	6/6/2019	6/13/2019
530568	4VZVU1E92LC086324	2020	KG	DB	4549	S	11/29/2018	12/6/2018
530575	4VZVU1E91LC086329	2020	KG	DB	4531	S	2/11/2019	2/18/2019
530584	4VZVU1E94KC087408	2020	KG	DB	4531	S	5/20/2019	5/31/2019
530590	4VZVU1E94KC087425	2020	KG	DB	4531	S	5/28/2019	6/6/2019
710592	4UZACEFC8LCLL5967	2020	NA	DP	3343	FL	11/27/2018	12/4/2018
710610	4UZACEFE3LCLH3717	2020	NA	DP	3545	FL	2/8/2019	2/15/2019
710637	4UZACEFC8LCLW2389	2020	NA	DP	3343	FL	5/22/2019	6/3/2019
710641	4UZACEFC3LCLW7676	2020	NA	DP	3343	FL	5/24/2019	6/4/2019
710642	4UZACEFC4LCLW2387	2020	NA	DP	3341	FL	6/5/2019	6/12/2019
710728	4UZACEFE8LCLX0025	2020	NA	DP	3545	FL	6/6/2019	6/13/2019
801353	4UZFCFTG3LCLL5968	2020	EX	DP	4533	FL	12/12/2018	12/19/2018
801356	4VZVU1E98LC086327	2020	EX	DP	4569	S	1/29/2019	2/7/2019
801362	4VZVU1E94KC086887	2020	EX	DP	4533	S	5/22/2019	6/4/2019
904747	4UZFCFTM5LCLL6156	2020	MA	DP	4551	FL	1/11/2019	1/24/2019
904752	4VZVU1E98LC086330	2020	MA	DP	4002	S	2/7/2019	2/15/2019
904763	4VZVU1E96LC087170	2020	MA	DP	4551	S	5/20/2019	5/29/2019
904764	4UZFCFTM2LCLW3735	2020	MA	DP	4543	FL	5/24/2019	6/5/2019
904765	4VZVU1E9XLC087544	2020	MA	DP	4543	S	5/31/2019	6/7/2019
904772	4UZFCFTM0LCLX7424	2020	MA	DP	4551	FL	6/5/2019	6/12/2019
904783	4UZFCFTM2LCLX7425	2020	MA	DP	4551	FL	6/7/2019	6/14/2019