



TECHNICAL BULLETIN

29 AUG 2019

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

This bulletin supersedes TSB LTB01298NAS1/2019 dated 10 MAY 2019, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page). Only refer to the electronic version of this Technical Bulletin in TOPIx.

Changes are highlighted in blue

SECTION:

303-14

SUBJECT /CONCERN:

Delayed Throttle Response When Accelerating From Low Vehicle Speed

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
Discovery (LR)	2018-2019	032671-096624	Solihull	V6 S/C 3.0L Petrol
Discovery (LR)	2019	400085-414715	Nitra (Slovakia)	V6 S/C 3.0L Petrol
Range Rover Sport (LW)	2018	690434-699998	Solihull	V6 S/C 3.0L Petrol
Range Rover Sport (LW)	2018	181330-199994	Solihull	V6 S/C 3.0L Petrol
Range Rover Sport (LW)	2018-2019	400000-427053	Solihull	V6 S/C 3.0L Petrol
Range Rover Sport (LW)	2018-2019	800064-852818	Solihull	V6 S/C 3.0L Petrol
Range Rover (LG)	2018-2019	382256-567623	Solihull	V6 S/C 3.0L Petrol

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:**SITUATION:**

A momentary delayed throttle response may be experienced when accelerating from low vehicle speed.

CAUSE:

Software error.

ACTION:

Follow the instructions below.

TOOLS:



E208514

Jaguar Land Rover (JLR)
approved diagnostic
equipment



61 71230

JLR approved battery
support unit

WARRANTY:

NOTES:

- Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.
- The JLR claims submission system requires the use of causal part numbers. Labor only claims must show the causal part number with a quantity of zero.

DESCRIPTION	SRO	TIME (HOURS)	CONDITION CODE	CAUSAL PART
Powertrain Control Module (PCM) - Update ECU	85.18.03	0.2	04	LR084286

 **NOTE:**

Normal Warranty procedures apply.

1.

⚠ CAUTION:

This procedure requires a minimum of Pathfinder 240 installed or later.

△ NOTES:

- The JLR approved diagnostic equipment will read the Vehicle Identification Number (VIN) for the vehicle and automatically take the vehicle out of 'Transportation Mode' if required.
- All ignition ON/OFF instructions must be followed. Failure to complete these instructions may cause damage to the vehicle control modules.

Connect the JLR approved battery support unit.

2.

Connect the JLR approved diagnostic equipment to the vehicle and begin a new session.

3.

Follow the JLR approved diagnostic equipment prompts.

- Select 'ECU Diagnostics'.
- Select 'Powertrain Control Module [PCM]'.
- Select 'Update ECU'.
- Follow all on-screen instructions to complete the task.

4.

If required, reset the vehicle to 'Transportation mode'.

5.

When all of the tasks are complete, exit the session.

6.

Disconnect the JLR approved diagnostic equipment and the JLR approved battery support unit.