

# UPDATE PRIOR TO SALE N352 UPS6619-5B - VISCOUS COOLING FAN PULLEY ALIGNMENT



NAS19.07.016 | WORKSHOP  
ISSUE 2

CAN/USA

AFTERSALES BULLETIN  
AUGUST 1, 2019

**NOTE:** this bulletin updates/supersedes all previous versions. Changes are highlighted in blue.

## DESCRIPTION OF ISSUE

A potential issue has been identified on a limited number of vehicles within the listed Affected Vehicle Range where the viscous cooling fan pulley was installed onto the engine using an alignment rig that did not accurately control its position during installation. There is a potential impact to the front end accessory drive system leading to loss of drive to accessories.

This program does not apply to any vehicle already registered and in use, either with the retailer or customer. Any vehicle already in use may continue to be driven and any repair instructions deemed necessary will be communicated through a separate Field Action or Technical Bulletin.

## AFFECTED VEHICLE RANGE

Range Rover Sport (L494; Ingenium I6 3.0L Petrol)

Model Year: ..... 2019

VIN: ..... 859790-863298

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your retailer.

## SERVICE PROGRAM / REWORK ACTION

Retailers will measure the gap between the viscous cooling fan pulley and the viscous cooling fan bracket prior to delivery to the customer.

If the vehicle fails the inspection, the viscous cooling fan pulley, bracket, drive belt will be replaced.

## ACTION TO BE TAKEN

Use the Jaguar Land Rover claims submission system to make sure that a vehicle is eligible for this program prior to undertaking any rework action.

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action.

Refer to Technical Bulletin N352 [UPS6619-5bNAS](#), *Update Prior to Sale: Viscous Cooling Fan Pulley Alignment*, for detailed repair instructions.

## PARTS

**NOTE:** only order parts for a vehicle after performing the inspection procedure in the Technical Bulletin noted.

Use the Vehicle Identification Number (VIN) and the Electronic Parts Catalog (EPC) to confirm part number(s) necessary to perform repairs.

DESCRIPTION	PART NUMBER	QUANTITY
Fan pulley bracket	LR121782	1
Fan pulley	LR121783	1
Belt fan drive	LR123070	1
Fan pulley bolt(s)	FS108186	4

Jaguar Land Rover North America, LLC  
100 Jaguar Land Rover Way  
Mahwah, NJ 07495

DESCRIPTION	PART NUMBER	QUANTITY
Fan pulley bracket bolt(s)	FB108076	3

## TOOLS

Refer to Technical Bulletin noted above for any required tools.

## WARRANTY

**NOTE:** use the Jaguar Land Rover claims submission system to make sure that a vehicle is eligible for this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, make sure that all outstanding Recall and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in/drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the July 26, 2021, closure date must be submitted or payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PART NUMBER(S)	QUANTITY
<b>N352</b>	<b>A</b>	Inspect viscous cooling fan pulley and the viscous cooling fan bracket gap	26.25.19	0.4	-	-
<b>N352</b>	<b>B</b>	Inspect viscous cooling fan pulley and the viscous cooling fan bracket gap	26.25.19	0.4	-	-
		Drive in/drive out	02.02.02	0.2	-	-
<b>N352</b>	<b>C</b>	Renew - Viscous cooling fan pulley, viscous cooling fan bracket and viscous cooling fan drive belt	26.25.89.01	0.6	LR121782 LR121783 LR123070 FS108186 FB108076	1 1 1 4 3
<b>N352</b>	<b>D</b>	Renew - Viscous cooling fan pulley, viscous cooling fan bracket and viscous cooling fan drive belt	26.25.89.01	0.6	LR121782 LR121783 LR123070 FS108186 FB108076	1 1 1 4 3
		Drive in / drive out	02.02.02	0.2	-	-

*Normal Warranty policies and procedures apply.*

## **CUSTOMER COMMUNICATION**

Should this Program mean that you are unable to deliver an affected vehicle to a customer at an agreed handover date, please advise the customer of the following:

*'Jaguar Land Rover is committed to delivering vehicles to our customers of the highest quality, complete with the very latest hardware and software. Our vehicles are continually evolving, with our Engineering and Design teams constantly looking for new and innovative ways to further enhance and develop our vehicles.*

*Jaguar Land Rover has advised us that there is an upgrade to be carried out on your vehicle, and have instructed us to complete this action prior to handing the vehicle over to you. Jaguar Land Rover apologize that this upgrade may delay the delivery of your new vehicle but are committed to ensuring customers benefit from the very latest technology to ensure your ownership experience is the best one possible.'*

If necessary, you may communicate technical details of the repair or upgrade that is required on the vehicle; this is at your discretion.

## **RETAILER EMPOWERMENT**

We appreciate the frustration experienced by both our customers and Retailers with regards the launch of any Update Prior to Sale program.

Following the launch of Retailer Empowerment (and where you feel it appropriate), you now have the ability to offer goodwill to customers who have suffered delays in the delivery of their vehicle. Any goodwill offer should be specifically for a customer whose vehicle delivery has been delayed due to this specific activity to acknowledge the poor experience.

Should you have any questions, please contact the Customer Relationship Centre (CRC) in the first instance for help and support.