

Technical Service Bulletin

92 Windshield wiper on left side makes contact with the left A-pillar

92 19 21 2056133/1 September 11, 2019.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment	
Q3	2019 – 2020	All	Not Applicable	

Condition

Customer states:

• The left windshield wiper blade intermittently makes contact with the Apillar while driving. When the vehicle is inspected in the workshop the symptom cannot be replicated.

Workshop findings:

• The 'parked' wiper arm position is checked to the specified dimension of 44.1mm (+10mm) on the left and 41.5mm (+10mm) on the right. It is found to be within specification on both sides (Figure 1).



Side	Adjustment Dimension -a- in mm	
Driver side	44.1 *10	
Front passenger side	41.5 *10	

Figure 1. Windshield wiper adjustment specifications.

Page 1 of 2

^{© 2019} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Technical Service Bulletin

Technical Background

When the vehicle is traveling at a speed between 4 km/h (~3 mph) and 100 km/h (~62 mph) and the windshield wiper system set to position 2 (slow wiping) or 3 (fast wiping) the windshield wiper motor extends the wiping stroke every third stroke. On the third stroke, the left wiper blade will make slight contact with the left A-pillar (Figure 2).



Figure 2. Windshield wiper operating modes.

Production Solution

None. This is an intended function implemented to clear additional debris from the wiper blade. This function is not active below speeds of 4 km/h (~3 mph) and above speeds of 100 km/h (~62 mph).

Service

Make no repairs or alter the specified wiper adjustment in an attempt to change this operation.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2056133) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2019 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

^{© 2019} Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.