



SERVICE BULLETIN

Classification:

BT19-014

Reference:

NTB19-070

Date:

September 12, 2019

RATTLE FROM HEAT SHIELD

APPLIED VEHICLES: 2018 – 2019 Armada (Y62)

IF YOU CONFIRM

There is a rattle noise coming from the right front of the vehicle when the engine is running or when turning the steering wheel, or when driving at parking lot speeds.

ACTION

Adjust the clearance between the rear cooler pipe and the heat shield above the exhaust front tube (RH) to 6 mm,

AND

Adjust the clearance between the heat shield above the exhaust front tube (RH) and the frame to 10 mm.

IMPORTANT: The purpose of ACTION (above) is to give you a quick idea of the work you will be performing. You **MUST** closely follow the entire SERVICE PROCEDURE as it contains information that is essential to successfully completing this repair.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

1. Locate the heat shield above the exhaust front tube (RH).




Figure 1

2. Locate the rear heater pipes on the upper **inboard** side of the frame.

3. Locate the rear cooler pipes on the upper **outboard** side of the frame.




Figure 2

4. Use your hands to adjust the clearance between the heat shield and the top side of the frame to 10 mm.




Figure 3

5. Use your hands to adjust the clearance between the rear cooler and heater pipe assembly and the heat shield to 6 mm.




Figure 4

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Adjust heat shield and Rear cooler and heater pipe	(1)	FX64AA	ZL	32	0.3 hrs.

(1) Reference the electronic parts catalog and use the Lower Dash Insulator (67354-*****) as the Primary Failed Part (PFP).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
September 12, 2019	NTB19-070	Original bulletin published

