



Bulletin No.: PIP5664A

Published date: N/A

## Preliminary Information

### PIP5664A DTCs P11CC P11D5 P20EE P226D P249E P249D

#### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500/3500	2020	All	All	6.6 L5P	All
GMC	Sierra 2500/3500	2020	All	All	6.6 L5P	All

Involved Region or Country	North America
Condition	A customer may have a concern of a check engine light on.
Cause	The technician may find DTCs P11CC, P11D5, P20EE, P226D, P249E and / or P249D set.

#### Correction:

If DTCs P11CC, P11D5, P20EE, P226D, P249E and/or P249D are found perform the following:

1. NOx Sensor 1 Reset.
2. NOx Catalyst Reductant Loading Reset.
3. Clear the DTC.
4. Set up for a regeneration enable. DO NOT perform a service regeneration.
5. Return the vehicle to the customer.

If DTC P226D is the only DTC found:

1. Clear the DTC.
2. Return the vehicle to the customer.

GM engineering is aware of these concerns and is working on a solution.

#### Warranty Information

For vehicles repaired under the Emission coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2886398	DTC P226D Reset	.2 hrs.
4087068	DTC P11CC, P11D5, P20EE, P226D, P249E OR P249D Procedure	.4 hrs.
*This is a unique Labor Operation for Bulletin use only.		

#### Version History

Version	2
Modified	08/01/2019 - Created on. 09/03/2019 - Updated to include DTC P11D5.



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.