

Technical Information

Service

34/19 ENU 3965

3

Complaint - Repair Instructions in the Event of Transfer Case Oil Leaks: Follow recommended course of action (34/19)

Model Line: Cayenne (92A)

Model Year: As of 2011 up to 2018

Subject: Transfer Case

Information: Measures and repair instructions for repairing oil leaks on the transfer case depending on the


exact location of the leak.

Note: Transfer case is also known as Transfer gear.

Remedial Before doing any other work, identify the exact cause(s) of the leak(s) based on the examples and carry

Action: out the relevant repair measure(s).

Overview - Location of leaks on transfer gear



Location of leaks (transfer gear)

- 1 Rear transfer gear housing (oil coating)
- Front transfer gear housing (bottom) (oil leak/oil coating)
- Lower transfer gear housing (oil coating)

3965 ENU **34/19**

Technical Information

Overview — Location of leaks and exact leak area, possible causes and repair measures

You will find detailed repair descriptions for the relevant leak areas at the end of this overview.

Leak	Leak area	Possible cause	Repair measure/procedure
1 – Rear transfer gear housing	Leak areas 1A - 1C	Sealing ring on rear output shaft leaking	Replace sealing ring on output shaft for rear transfer gear. For instructions, see description of leak areas 1A – 1C below.
		Sealing ring on drive shaft for transfer gear leaking	Replace inner sealing ring on drive shaft for transfer gear. For instructions, see description of leak area 2A below.
2 – Front transfer gear housing (bottom)	Leak area 2	Sealing ring on output shaft for main transmission leaking	Replace rear sealing ring on output shaft for main transmission. For instructions, see description of leak area 2B below.
		Transfer gear housing leaking (cracked)	Replace transfer gear. For instructions, see description of leak area 2C below.
3 – Lower transfer	Leak area 3	Sealing ring on output shaft for front transfer gear leaking	Replace sealing ring on output shaft for front transfer gear. For instructions, see description of leak area 3A below.
gear housing		Rear left transfer gear housing leaking (sealant defective)	Replace transfer gear. For instructions, see description of leak area 3B below.

Technical Information	Servic	е		7
	34/19	ENU	3965	<u> </u>

Outer right transfer gear housing leaking (sealant defective)	Replace transfer gear. For instructions, see description of leak area 3C below.
Oil leak from leak area "Front transfer gear housing (bottom)"	See Location of leak "2 – Front transfer gear housing (bottom)"

1 - Rear transfer gear housing - Damage, possible causes and repair measures


Work In the event of leaks on the rear transfer gear housing, check possible cause(s) and carry out the

Procedure: suggested repair measure.

Leak areas

(1A-1C): Leak areas 1A and 1B

Rear transfer gear in output shaft area (⇒ Rear transfer gear — output shaft area): Oil coating, with some drops forming (⇒ Rear transfer gear — output shaft area -Arrows-)




Rear transfer gear — output shaft area

3965 ENU 34/19

Technical Information

Leak area 1C

Rear transfer gear in lower housing area (\Rightarrow Rear transfer gear — lower housing area): Coating of oil (\Rightarrow Rear transfer gear — lower housing area -Arrows-)



Rear transfer gear — lower housing area

Cause (1A-1C): Cause of leaks at leak areas 1A-1C: Sealing ring on output shaft for rear transfer gear leaking

⇒ Sealing ring leaking



Sealing ring leaking

Repair measure Replace sealing ring on output shaft for rear transfer gear, see \Rightarrow Workshop Manual '399255 Replacing (1A-1C): sealing ring for transfer gear (rear output shaft)'.

Parts required (1A-1C):	Part No.	Designation – Use	Qty.
	958 341 199 00	\Rightarrow Sealing ring (35 x 72 x 8)	1 ea.
		 Output shaft for rear transfer gear 	
	N 900 639 05	\Rightarrow Hex flange bolt, M8 X 18	4 ea.
		– Damper to transfer gear	
	958 349 493 00	⇒ Circlip	2 ea.
		 Rear cardan shaft to rear axle differential/transfer gear 	
	958 111 220 XX ¹⁾	⇒ Clamping sleeve	X ea. ²⁾
		- Exhaust system	
	955 301 115 01	⇒ Screw plug	1 ea.
		 Oil inspection plug on transfer gear 	

34/19 ENU 3965

3

Required materials (1A-1C):

Additional materials required for vehicles with hang-on transfer gear:

Sample Porsche part number.

Part No. Designation Qty.

 $000\,043\,305\,63$ \Rightarrow Transfer gear oil 0.85-liter container

(smaller quantity as required)

Additional materials required for vehicles with Torsen transfer gear:

Sample Porsche part number.

Part No. Designation Qty.

958 341 536 00 \Rightarrow Transfer gear oil 1-liter container

(smaller quantity as required)



Information

Only the quantities that are actually added must be invoiced when using original Porsche fluids. Invoicing of 1-liter container is not permitted.

Labor operations (1A-1C):

LO	Designation
39925550	Replacing sealing ring for transfer gear
39903550	Checking and topping up oil for final drive
393519XX ¹⁾	Removing and installing rear cardan shaft

¹⁾ The relevant labour operation for each vehicle type must be determined using the PCSS by specifying the VIN.

PQIS coding: For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	39650	Transfer gear
Damage type (SA4)	5400	Oil leak

2 - Front transfer gear housing (bottom) - Damage, possible causes and repair measures

Work In the event of leaks on the front transfer gear housing (bottom), check possible cause(s) and carry out

Procedure: the suggested repair measure(s).

¹⁾ The complete part number must be determined for each vehicle using PET2.


²⁾ The actual number of clamping sleeves required for each vehicle type must be determined using PET2.

3965 ENU 34/19

Technical Information

Leak area (2): Leak area 2


Front transfer gear (⇒ Front transfer gear housing (bottom)): Oil leak/oil coating in area where it joins main transmission (⇒ Front transfer gear housing (bottom) - Arrows-)



Front transfer gear housing (bottom)

Cause (2A): Sealing ring on drive shaft for transfer gear leaking

 \Rightarrow Sealing ring leaking



Sealing ring leaking

Repair measure Replace sealing ring for transfer gear, see \Rightarrow Workshop Manual '399255 Removing and installing sealing (2A): ring for transfer gear (inner drive)'.

Parts required (2A):	Part No.	Designation - Use	Qty.
	958 341 199 20	\Rightarrow Sealing ring (55 x 80 x 8)	1 ea.
		 Drive shaft for transfer gear 	
	WHT 003 211	⇒ 12 point socket	10 ea.
		– Transfer gear screws	
	N 909 913 02	\Rightarrow Hex flange bolt (combination)	4 ea.
		 Cross member to outer body 	
	N 105 167 02	⇒ Hex flange bolt, self-locking	2 ea.
		 Cross member to inner body 	

N 900 639 05	⇒ Hex flange bolt	4 ea.
	 Damper to transfer gear 	
958 349 493 00	⇒Circlip	1 ea.
	 Rear cardan shaft to transfer gear 	
958 349 490 10	⇒Circlip	1 ea.
	 Front cardan shaft to front-axle final drive 	
958 349 491 10	⇒ Circlip	1 ea.
	- Front cardan shaft to transfer gear	
955 301 115 01	⇒ Screw plug	1 ea.
	 Oil inspection plug on transfer gear 	
958 111 220 XX ¹⁾	⇒ Clamping sleeve	X ea. ²⁾
	– Exhaust system	

¹⁾ The complete part number must be determined for each vehicle using PET2.

²⁾ The actual number of clamping sleeves required for each vehicle type must be determined using PET2.

Required	Part No.	Designation	Qty.
materials (2A):	000 043 305 73	⇒ Extreme pressure grease	100g tube
			(approx. 5–10 grams required
			per vehicle)

Additional materials required for vehicles **with** hang-on transfer gear:

Sample Porsche part number.

Part No.DesignationQty.000 043 305 63⇒ Transfer gear oil0.85-liter container
(smaller quantity as required)

Additional materials required for vehicles with Torsen transfer gear:

Sample Porsche part number.

Part No.	Designation	Qty.
958 341 536 00	⇒ Transfer gear oil	1-liter container
		(smaller quantity as required)



Information

Only the quantities that are actually added must be invoiced when using original Porsche fluids. Invoicing of 1-liter container is not permitted.

3965 ENU 34/19

Technical Information

Labor operations (2A):


LO	Designation
39925552	Replacing sealing ring for transfer gear
39903550	Checking and topping off oil for final drive
396519XX ¹⁾	Removing and installing transfer gear

¹⁾ The relevant labor operation for each vehicle type must be determined using the PCSS by specifying the VIN.

PQIS coding: For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	39650	Transfer gear
Damage type (SA4)	5400	Oil leak

Cause (2B): Sealing ring on output shaft for main transmission leaking ⇒ Sealing ring leaking



Sealing ring leaking

Repair measure Replace sealing ring on rear output shaft, see \Rightarrow Workshop Manual '387055 Replacing sealing ring for (2B): rear output shaft'.

Part No.	Designation	Qty.
	- Use	
955 321 189 00	\Rightarrow Sealing ring (41 x 72 x 11)	1 ea.
	 Output shaft for main transmission 	
WHT 003 211	\Rightarrow 12 point socket	10 ea.
	– Transfer gear screws	
N 909 913 02	⇒ Hex flange bolt (combination)	4 ea.
	- Cross member to outer body	
	955 321 189 00 WHT 003 211	- Use 955 321 189 00 ⇒ Sealing ring (41 x 72 x 11) - Output shaft for main transmission WHT 003 211 ⇒ 12 point socket - Transfer gear screws N 909 913 02 ⇒ Hex flange bolt (combination)

Technical Information Service 34/19 ENU 3965

⇒ Hex flange bolt, self-locking	2 ea.
 Cross member to inner body 	
⇒ Hex flange bolt	4 ea.
– Damper to transfer gear	
⇒ Circlip	1 ea.
- Rear cardan shaft to transfer gear	
⇒ Circlip	1 ea.
- Front cardan shaft to front-axle final drive	
⇒ Circlip	1 ea.
- Front cardan shaft to transfer gear	
⇒ Sealing ring	1 ea.
– ATF inspection plug	
⇒ Clamping sleeve	X ea. ²⁾
– Exhaust system	
	- Cross member to inner body ⇒ Hex flange bolt - Damper to transfer gear ⇒ Circlip - Rear cardan shaft to transfer gear ⇒ Circlip - Front cardan shaft to front-axle final drive ⇒ Circlip - Front cardan shaft to transfer gear ⇒ Sealing ring - ATF inspection plug ⇒ Clamping sleeve

¹⁾ The complete part number must be determined for each vehicle using PET2.

Required materials (2B):

Sample Porsche part number.

Part No.	Designation	Qty.
000 043 305 73	⇒ Extreme pressure grease	100g tube
		(approx. 5–10 grams required
		per vehicle)
000 043 305 05	\Rightarrow Transmission oil	1-liter container
		(smaller quantity as required)



Information

Only the quantities that are actually added must be invoiced when using original Porsche fluids. Invoicing of 1-liter container is not permitted.

Labor operations (2B):

LO	Designation
38705550	Replacing output shaft seal
37023550	Checking and topping off ATF
396519XX ¹⁾	Removing and installing transfer gear

¹⁾ The relevant labor operation for each vehicle type must be determined using the PCSS by specifying the VIN.

PQIS coding: For invoicing and documentation using PQIS, enter the following coding:

²⁾ The actual number of clamping sleeves required for each vehicle type must be determined using PET2.

3

Service


3965 ENU 34/19

Technical Information

Location (FES5)	39650	Transfer gear
Damage type (SA4)	5400	Oil leak

Cause (2C): Transfer gear housing leaking (cracked)

⇒ Transfer gear housing leaking (cracked)



Transfer gear housing leaking (cracked)

Repair measure Replace transfer gear, see \Rightarrow Workshop Manual '396519 Removing and installing transfer gear'. (2C):

Parts required	Part No.	Designation	Qty.
(2C):		- Use	
	958 341 010 XX ¹⁾	Hang-on transfer gear	1 ea.
	or		
	958 341 020 XX ¹⁾	Torsen transfer gear	1 ea.
	WHT 003 211	⇒ 12 point socket	10 ea.
		– Transfer gear screws	
	N 909 913 02	\Rightarrow Hex flange bolt (combination)	4 ea.
		 Cross member to outer body 	
	N 105 167 02	\Rightarrow Hex flange bolt, self-locking	2 ea.
		 Cross member to inner body 	
	N 900 639 05	\Rightarrow Hex flange bolt	4 ea.
		– Damper to transfer gear	
	958 349 493 00	⇒ Circlip	1 ea.
		 Rear cardan shaft to transfer gear 	
	958 349 490 10	⇒ Circlip	1 ea.
		 Front cardan shaft to front-axle final drive 	
	958 349 491 10	⇒ Circlip	1 ea.
		- Front cardan shaft to transfer gear	

Technical Information

Service

34/19 ENU 3965

955 301 115 01

 \Rightarrow Screw plug

1 ea.

958 111 220 XX ¹⁾

Oil inspection plug on transfer gear⇒ Clamping sleeve

X ea. 2)

- Exhaust system

Required materials (2C)

Part No.

Designation

Qty.

materials (2C): 000 043 305 73

⇒ Extreme pressure grease

100g tube

(approx. 5-10 grams required

per vehicle)

Additional materials required for vehicles with hang-on transfer gear:

Sample Porsche part number.

Part No.

Designation

Qty.

0.85-liter container

000 043 305 63

⇒ Transfer gear oil

(smaller quantity as required)

Additional materials required for vehicles with Torsen transfer gear:

Sample Porsche part number.

Part No.

Designation

Qty.

958 341 536 00

⇒ Transfer gear oil

1-liter container

(smaller quantity as required)



Information

Only the quantities that are actually added must be invoiced when using original Porsche fluids. Invoicing of 1-litre container is not permitted.

Labor operations (2C):

LO	Designation
39903550	Checking and topping off oil for final drive
396519XX ¹⁾	Removing and installing transfer gear

¹⁾ The relevant labor operation for each vehicle type must be determined using the PCSS by specifying the VIN.

¹⁾ The complete part number must be determined for each vehicle using PET2.

²⁾ The actual number of clamping sleeves required for each vehicle type must be determined using PET2.

3965 ENU 34/19

Technical Information

PQIS coding: For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	39650	Transfer gear
Damage type (SA4)	5400	Oil leak

3 - Lower transfer gear housing - Damage, possible causes and repair measures



Information


- A (misleading) coating of oil on the bottom of the transfer gear (front and/or rear) can be caused by a minimal leak on one of the drive train components (engine, main transmission, steering gear or front-axle final drive).
- This is an oil leak caused by heat and air flow while driving.
- The component(s) responsible for this must be checked while warm by performing a leak test. The leak must then be corrected if necessary and the transfer gear must be cleaned carefully.

Work Procedure:

In the event of leaks on the lower transfer gear housing, check possible cause(s) and carry out the suggested repair measure(s).

Leak area (3): Leak area 3

Front transfer gear in lower housing area (⇒ Front transfer gear — lower housing area): Coating of oil (⇒ Front transfer gear — lower housing area - Arrows-)



Front transfer gear — lower housing area

34/19 ENU 3965

Cause (3A): Sealing ring on output shaft for front transfer gear leaking

⇒ Sealing ring leaking



Sealing ring leaking

Repair measure Replace sealing ring on output shaft for front transfer gear, see \Rightarrow Workshop Manual '399255 Replacing (3A): sealing ring for transfer gear (front output shaft)'.

Parts required (3A):	Part No.	Designation - Use	Qty.
	958 341 199 10	⇒ Sealing ring (35 x 62 x 8)– Output shaft for front transfer gear	1 ea.
	958 349 490 10	⇒ Circlip– Front cardan shaft to front-axle final drive	1 ea.
	958 349 491 10	⇒ Circlip– Front cardan shaft to transfer gear	1 ea.
	955 301 115 01	⇒ Screw plugOil inspection plug/oil drain plug on transfer gear	2 ea.

Required materials (3A):

Additional materials required for vehicles with hang-on transfer gear:

Sample Porsche part number.

Part No.DesignationQty.000 043 305 63⇒ Transfer gear oil0.85-liter container

(smaller quantity as required)

Qty.

Additional materials required for vehicles **with** Torsen transfer gear:

Designation

Sample Porsche part number.

Part No.

958 341 536 00 ⇒ Transfer gear oil 1-liter container

(smaller quantity as required)

3965 ENU 34/19

Technical Information



Information

Only the quantities that are actually added must be invoiced when using original Porsche fluids. Invoicing of 1-liter container is not permitted.

Labor operations (3A):


LO	Designation
39925551	Replacing sealing ring for transfer gear
39021920	Removing and installing front cardan shaft
39905556	Changing oil for final drive

PQIS coding: For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	39650	Transfer gear
Damage type (SA4)	5400	Oil leak

Cause (3B): Rear left transfer gear housing leaking (sealant defective)

⇒ Rear left transfer gear housing leaking



Rear left transfer gear housing leaking

Repair measure Replace transfer gear, see \Rightarrow Workshop Manual '396519 Removing and installing transfer gear'. (3B):

34/19 ENU 3965

	_
	7
	≺
)
•	

Parts required (3B):	Part No.	Designation – Use	Qty.
	958 341 010 XX ¹⁾	Hang-on transfer gear	1 ea.
	or		
	958 341 020 XX ¹⁾	Torsen transfer gear	1 ea.
	WHT 003 211	⇒ 12 point socket	10 ea.
	N 000 040 00	- Transfer gear screws	
	N 909 913 02	⇒ Hex flange bolt (combination)– Cross member to outer body	4 ea.
	N 105 167 02	⇒ Hex flange bolt, self-locking	2 ea.
		– Cross member to inner body	
	N 900 639 05	⇒ Hex flange bolt	4 ea.
		- Damper to transfer gear	
	958 349 493 00	⇒ Circlip	1 ea.
		 Rear cardan shaft to transfer gear 	
	958 349 490 10	⇒ Circlip	1 ea.
		- Front cardan shaft to front-axle final drive	
	958 349 491 10	⇒ Circlip	1 ea.
		- Front cardan shaft to transfer gear	
	955 301 115 01	⇒ Screw plug	1 ea.
		 Oil inspection plug on transfer gear 	
	958 111 220 XX ¹⁾	⇒ Clamping sleeve – Exhaust system	X ea. ²⁾
		- Exhaust system	

¹⁾ The complete part number must be determined for each vehicle using PET2.

²⁾ The actual number of clamping sleeves required for each vehicle type must be determined using PET2.

Required	Part No.	Designation	Qty.
materials (3B):	000 043 305 73	⇒ Extreme pressure grease	100g tube
			(approx. 5-10 grams required
			per vehicle)

Additional materials required for vehicles with hang-on transfer gear:

Sample Porsche part number.

Part No.	Designation	Qty.
000 043 305 63	⇒ Transfer gear oil	0.85-liter container
		(smaller quantity as required)

Additional materials required for vehicles **with** Torsen transfer gear:

Sample Porsche part number.

3965 ENU 34/19

Technical Information

Part No. Designation

958 341 536 00 \Rightarrow Transfer gear oil

Qty.

1-liter container (smaller quantity as required)



Information

Only the quantities that are actually added must be invoiced when using original Porsche fluids. Invoicing of 1-liter container is not permitted.

Labor operations (3B):

LO	Designation
39903550	Checking and topping off oil for final drive
396519XX ¹⁾	Removing and installing transfer gear


¹⁾ The relevant labor operation for each vehicle type must be determined using the PCSS by specifying the VIN.

PQIS coding: For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	39650	Transfer gear
Damage type (SA4)	5400	Oil leak

Cause (3C): Outer right transfer gear housing leaking (sealant

⇒ Outer right transfer gear housing leaking



Outer right transfer gear housing leaking

Repair measure Replace transfer gear, see \Rightarrow Workshop Manual '396519 Removing and installing transfer gear'. (3C):

Parts required (3C):	Part No.	Designation - Use	Qty.
, ,	958 341 010 XX ¹⁾	Hang-on transfer gear	1 ea.
	or		
	958 341 020 XX ¹⁾	Torsen transfer gear	1 ea.
	WHT 003 211	⇒ 12 point socket– Transfer gear screws	10 ea.
	N 909 913 02	⇒ Hex flange bolt (combination)– Cross member to outer body	4 ea.
	N 105 167 02	⇒ Hex flange bolt, self-locking– Cross member to inner body	2 ea.
	N 900 639 05	⇒ Hex flange bolt – Damper to transfer gear	4 ea.
	958 349 493 00	⇒ Circlip – Rear cardan shaft to transfer gear	1 ea.
	958 349 490 10	⇒ Circlip – Front cardan shaft to front-axle final drive	1 ea.
	958 349 491 10	⇒ Circlip - Front cardan shaft to transfer gear	1 ea.
	955 301 115 01	⇒ Screw plug – Oil inspection plug on transfer gear	1 ea.
	958 111 220 XX ¹⁾	⇒ Clamping sleeve – Exhaust system	X ea. ²⁾

¹⁾ The complete part number must be determined for each vehicle using PET2.

²⁾ The actual number of clamping sleeves required for each vehicle type must be determined using PET2.

Required	Part No.	Designation	Qty.
materials (3C):	000 043 305 73	⇒ Extreme pressure grease	100g tube
			(approx. 5–10 grams required
			per vehicle)

Additional materials required for vehicles with hang-on transfer gear:

Sample Porsche part number.

Part No.	Designation	Qty.
000 043 305 63	⇒ Transfer gear oil	0.85-liter container
		(smaller quantity as required)

Additional materials required for vehicles with Torsen transfer gear:

Sample Porsche part number.

3965 ENU 34/19

Technical Information

Part No. Designation Qty.

958 341 536 00 ⇒ Transfer gear oil 1-liter container (smaller quantity as required)



Information

Only the quantities that are actually added must be invoiced when using original Porsche fluids. Invoicing of 1-liter container is not permitted.

Labor operations (3C):

LO	Designation
39903550	Checking and topping off oil for final drive
396519XX ¹⁾	Removing and installing transfer gear


¹⁾ The relevant labor operation for each vehicle type must be determined using the PCSS by specifying the VIN.

PQIS coding: For invoicing and documentation using PQIS, enter the following coding:

Location (FES5)	39650	Transfer gear
Damage type (SA4)	5400	Oil leak

Cause (3D): Oil leak/oil coating on bottom of front transfer gear housing (area where it joins main transmission)

⇒ Front transfer gear housing, bottom



Front transfer gear housing, bottom

Repair measure Leaks from the area where the transfer gear joins the main transmission can spread as far as the (lower)

transfer gear output shaft area, see "Front transfer gear housing (bottom) - Damage, possible

causes and repair measures".

References: ⇒ Workshop Manual '387055 Replacing sealing ring for rear output shaft'

(3D):

Technical Information

Service

34/19 ENU 3965

3

- ⇒ Workshop Manual '399255 Replacing sealing ring for transfer gear (rear output shaft)'
- ⇒ Workshop Manual '399255 Removing and installing sealing ring for transfer gear (inner drive)'
- ⇒ Workshop Manual '399255 Replacing sealing ring for transfer gear (front output shaft)'
- ⇒ Workshop Manual '396519 Removing and installing transfer gear'

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.