

Technical Information

29/13 ENU 9025

Service

9

Eliminating Symptoms in Body Interior: Re-programming Instrument Cluster Control Unit (Failure of TFT display in instrument cluster/SY 29/13)

Model Line:	911 (991) Boxster/Cayman (981)
Model Year:	As of 2012 up to 2014
Subject:	TFT display in instrument cluster
Symptom:	Customer complains that the TFT display stops working after the vehicle has been parked for a long time in the sun or during a long trip.
Cause:	An error in the software can cause the TFT display to stop working under the specified conditions.
Remedial Action:	Re-program instrument cluster control unit.
Date of Introduction:	An instrument cluster with updated software is installed during production in all vehicles as of production date March 10, 2014 .
Parts Info:	PCM3.1 Update CD (WKD95280015 or newer version)
Tools:	VAS 5908 - Battery Charger, 90 A 9900 - PIWIS Tester III

NOTICE

Fault entry in the fault memory and control unit programming aborted due to low voltage.

- Increased current draw during diagnosis or control unit programming can cause a drop in voltage, which can result in one or more fault entries and the abnormal termination of the programming process.
- ⇒ Before commencing work, connect a suitable battery charger or power supply, suitable for AGM type batteries, recommended current rating of 90A fixed voltage 13.5V to 14.5V.

NOTICE

Control unit programming will be aborted if the Internet connection is unstable.

- An unstable Internet connection can interrupt communication between PIWIS Tester and the vehicle communication module (VCI). As a result, control unit programming may be aborted.
- \Rightarrow During control unit programming, always connect PIWIS Tester to the vehicle communication module (VCI) via the USB cable.

DRAFT

NOTICE

Control unit programming will be aborted if the vehicle key is not recognized

- If the vehicle key is not recognized in vehicles with Porsche Entry & Drive, programming cannot be started or will be interrupted.
- ⇒ Switch on the ignition using the original vehicle key. To do this, replace the original vehicle key in the ignition lock with the plastic key fob if it was previously removed at the start of this procedure.
 - 1 Connect a battery charger with a current rating of **at least 90 A**. First connect the positive cable of the charger to the positive terminal of the battery and then connect the negative cable of the charger to the ground point for jump-lead starting.
 - 2 Switch on the ignition using the **original driver's key**. For vehicles with "Porsche Entry & Drive", replace the control panel in the ignition lock with the original driver's key, if necessary.
 - 3 **9900 PIWIS Tester III** must be connected to the vehicle communication module (VCI) via the **USB cable**. Then, connect the communication module to the vehicle and switch on the PIWIS Tester.

Work Procedure:

Re-program instrument cluster control unit:

4 On the PIWIS Tester start screen, call up the ⇒ 'Diagnostics' menu and select the relevant vehicle type.

The diagnostic application is then started and the control unit selection screen is populated.

- 5 In the control unit selection screen (⇒ 'Overview' menu), press F7" to call up the ⇒ 'Additional menu'.
- 6 When the question "Create Vehicle Analysis Log (VAL)?" appears, either press •F12" to create a VAL or press •F11" if you do not want to create a VAL.
- 7 Press •>>" to acknowledge the message informing you that campaigns for the vehicle are stored in the PIWIS information system.
- 8 Select the \Rightarrow 'Campaign' function and confirm your selection by pressing $\cdot >>$ ". You are then prompted to enter a campaign number.
- 9 To enter the campaign number, click in the relevant text box so that the cursor starts to flash.
- 10 Enter the programming code **C8K6B** and press Enter "to confirm.

The text box turns blue. Press $\bullet >>$ " to start the guided programming sequence.

Read the information and follow the prompts by pressing $\bullet >>$ " .

AfterSales

i Information

Read and follow the **information and instructions on the PIWIS Tester** during the guided programming sequence. **Do not interrupt programming and coding.**

i Information

Software version of the instrument cluster after programming has been carried out successfully: **0373**.

- 11 Once programming/coding has been carried out successfully, press •<<" to return to the overview.
- 12 Switch off the ignition.
- 13 Disconnect the PIWIS Tester from the vehicle.
- 14

i

Information

The values for the Tire Pressure Monitoring (TPM) system may be lost during re-coding of the instrument cluster.

If the Tire Pressure Monitoring (TPM) system is reset, you must select **Main menu** > **Tire pressure** > **Settings** in the instrument cluster to reset the **tire type** and **tire size**. The wheel position values will then be re-taught in the control unit during the **test drive** (at a speed of over **15 mph** or **25 km/h**).

To set the tire type and tire size, see \Rightarrow Owner's Manual, chapter Instrument Panel and Multi-Function Display - 'Tire Pressure Monitoring, TPM'.

15 On vehicles with Porsche Entry & Drive, replace the original vehicle key in the ignition lock with the control panel again.

Invoicing

The work involved is invoiced under the labor operation:

• 90252510: Re-programming instrument cluster control unit

For invoicing and documentation using PQIS, specify "90250" as the fault location (FES5) and "4042" as the damage category (SA4).

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2019 Porsche Cars North America, Inc.

Sep 10, 2019 Page 4 of 4

AfterSales