

SERVICE ACTION N356 - AUXILIARY COOLANT PUMP NOT ACTIVE



NAS19.09.010 | WORKSHOP

CAN/USA

AFTERSALES BULLETIN

SEPTEMBER 19, 2019

NOTE: this Service Action supersedes Update Prior to Sale UPS7419-1b with immediate effect.

DESCRIPTION OF ISSUE

A potential issue has been identified on a limited number of Land Rover vehicles within the listed Affected Vehicle Range where the auxiliary coolant pump has not been activated. This can result in shorter stop/start duration at lower ambient temperatures and reduced turbocharger life.

AFFECTED VEHICLE RANGE

Discovery (L462)

Model Year: 2019-2020

VIN: 056082-413339

Range Rover Sport (L494)

Model Year: 2019-2020

VIN: 188981-874018

Range Rover (L405)

Model Year: 2019-2020

VIN: 387462-564596

Visit the British Brands Sales Suite (BBSS) website for a list of affected vehicles at your retailer.

SERVICE PROGRAM / REWORK ACTION

An authorized Land Rover retailer will update the vehicle's Car Configuration File (CCF) prior to delivery to the customer. Affected vehicles already in the hands of customers should be updated at the next available opportunity. There will be charge to customers for this action under this program.

ACTION TO BE TAKEN

Use the Jaguar Land Rover claims submission system to make sure that the vehicle is affected by this program prior to undertaking any rework action.

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the rework action.

Refer to Technical Bulletin N356NAS, *Service Action - Auxiliary Coolant Pump Not Active*, for detailed repair instructions.

PARTS

No parts required.

TOOLS

Refer to Technical Bulletin noted above for any required tools.

WARRANTY

NOTE: use the Jaguar Land Rover claims submission system to make sure that a vehicle is affected by this program prior to undertaking any rework action.

Jaguar Land Rover North America, LLC
100 Jaguar Land Rover Way
Mahwah, NJ 07495

At the time of confirming a booking for vehicle repair, make sure that all outstanding Recall and Service Actions are identified to make sure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in/drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Use TOPIx to obtain the latest repair time.

This program is valid for a limited time only. Warranty claims with a repair date prior to the September 30, 2020 closure date must be submitted for payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)
N356	A	Car Configuration File (CCF) - Update	86.90.24	0.2
N356	B	Car Configuration File (CCF) - Update	86.90.24	0.2
		Drive in/drive out	02.02.02	0.2

Normal Warranty policies and procedures apply.