



Technical Service Bulletin

96 Time display in the instrument cluster and infotainment is fast or slow

96 19 44 2052836/2 October 22, 2019. Supersedes Technical Service Bulletin Group 96 number 18-29 dated November 5, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A5, A5 Cabriolet, RS5, and RS5 Cabriolet	2018	A000001 - A022343 Or N000001 - N006803	With analog instrument cluster
Q7	2017	All	With analog instrument cluster
Q7	2018	000001 - 004549	With analog instrument cluster

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Updated models) Revised <i>Service</i> (Added Note) Revised <i>Warranty</i> (Added Labor Operations) Revised <i>Required Parts and Tools</i> (Added table)
1	11/05/2018	Initial publication

Customer states:

- The clock is slow or loses time over a period of a week or two resulting in the clock being off by several minutes.
- This is found only in MMI systems without navigation, with the time master being the cluster.

Technical Background

A deviation of the accuracy of the quartz-controlled clock in the instrument cluster and infotainment display can deviate ± 1 second per day. This amounts to half a minute per month and is permissible.

Production Solution

Optimized parts in current series.



Technical Service Bulletin

Service

Check the accuracy of the quartz-controlled clock with a precise (e.g. satellite-controlled) clock for several days.

Scenario 1 Below or ± 1 second per day:

- If the deviation is ± 1 second per day or less, the quartz-controlled clock operates within the specification. Therefore no further repairs are necessary. Repairs cannot be accounted under warranty.

Scenario 2 Above ± 1 second per day:

If the test with another clock shows a deviation above the permissible guidelines of ± 1 second per day, follow the steps below:

- Using ODIS- right click on 17 Dash Board and select control module OBD.
- Select adaptation/parameter.
- Find source for synchronization of time.
- Change the source from internal clock to GPS.
- Select apply and enter login code 20103 to store.
- Disconnect the diagnostic head and close the hood, trunk, and doors then lock the vehicle for 15 minutes.
- Unlock the vehicle and go into date and time again to set the date and time using a known good source.



Note:

The above only applies to PR- I8S. For PR- I8E replacing the instrument cluster is necessary.

Warranty

Claim Type:	<ul style="list-style-type: none"> • 110 up to 48 Months/50,000 Miles. • G10 for CPO Covered Vehicles – Verify Owner. • If vehicle is outside any warranty, this Technical Service Bulletin is informational only. 		
Service Number:	9025		
Damage Code:	0040		
Labor Operations:	Instrument Cluster Replace (PR- I8E only)	9025 5500	See SRT
OR			



Technical Service Bulletin

Diagnostic Time:	GFF – Checking and clearing fault codes included in existing labor operations (PR- I8S only)	0150 0000	Time stated on the diagnostic protocol (Max 80 TU)
	Road test prior to service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2052836/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.



Note:

Can only claim the replacement of the instrument cluster or the diagnosis.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.		
Part Number	Part Description	Quantity
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA
8W6920870 * Or 4M0920870 *	Instrument Cluster	01

Additional Information

All part and service references provided in this TSB (2052836) are subject to change and/or removal.

©2019 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.