Technical Service Bulletin

Mazda North American Operations Irvine, CA 92618-2922



Subject: NEXT SERVICE DATE SETTING CHANGES TO MANUAL BY ITSELF AND/OR DISPLAYED AVERAGE FUEL ECONOMY GRADUALLY GETS WORSE WITHOUT RESET	Bulletin No.: 09-037/19		
	Last Issued: 10/16/2019		

APPLICABLE MODEL(S)/VINS

2019 Mazda3 (Japan built) vehicles with VINs lower than JM1BP*****142784 (produced before May 27, 2019)

2019 Mazda3 (Mexico built) vehicles with VINs lower than 3MZBP*****113637 (produced before May 28, 2019)

DESCRIPTION

Some customers may experience one or both of the following:

• The "Next Service Date" setting under Vehicle Status Monitor in the center display changes to "Manual" by itself after being set to "Automatic" and even with the "Manual" setting in the display, the internal calculation works as if set to "Automatic". The "Engine oil change" message is then displayed when the oil deterioration level reaches the threshold. This is caused by a communication error between the PCM, BCM and CMU.

	Vehicle Status Monitor
2. Select "Vehicle Status	n the Home screen to display the vehicle status monitor. Monitor". gs in the setup display as follows:
Item	Explanation
Vehicle Warning Messages	If there is a problem with the vehicle, information about the prob- lem is displayed.
Next Service	The next maintenance period is displayed. Date The date manually set by the customer is displayed. Distance If "Next Service Date" is set to "Automatic" The "Distance Until Oil Change" content is displayed. If "Next Service Date" is set to "Manual" The traveled distance manually set by the customer is displayed. However, when any of the following conditions is met, the "Dis- tance Until Oil Change" content is displayed. • You have not set the traveled distance. • "Distance Until Oil Change" is shorter than the traveled distance set by the customer.

Page 1 of 10

• The average fuel economy display in the instrument cluster gradually gets worse after 1,200 miles (2,000 km) of driving without a reset regardless of the actual driving situation. This concern is only present in the display and not in the actual fuel consumption.

To correct these issues, the software of the BCM has been modified.

REPAIR PROCEDURE

1. Perform BCM software update using Mazda Diagnostic And Repair Software (MDARS). Refer to "MDARS - ECU Reprogramming Procedure".

NOTE:

- For 5HB vehicles, also perform LFU software update. If LFU reprogramming is not performed, it may result in other concerns as stated in TSB 09-035/19.
- After the reprogramming, pending DTC P2610:00 [PCM] will be stored without the CHECK ENGINE light on. Start the engine and clear the DTC.
- If DTC U2120:00 or/and U2500:82 are stored and i-ACTIVSENSE warning light (amber) turns on after the reprogramming, refer to SA-036/19.

NOTE: If the current calibration file name on the ECU FILENAME screen is the same as shown below or with a later suffix, reprogramming is not necessary.

VIN	Body	BCM file name	BCM_SUB file name	LFU file name
Start with JM1	5HB	BEMD-66S02-J		BCWK-66S06-E
(Japan built)	4SD	BCKA-66S02-M	B0J8-66S03- (BCKB-66S03- for later suffix	N/A
Start with 3MZ (Mexico built)	4SD	BDTS-66S02-J	(BCKB-66S03- for later suffix BCM software)	N/A

2. Verify the repair.

MDARS ECU Reprogramming Procedure


NOTE: This procedure explains a generic reprogramming for all Electrical Control Units (ECU) such as PCM, BCM, ESU, etc. Be aware that some sentences and screen images below mention a certain control unit such as "PCM" or "BCM" as an example.

Page 2 of 10

ATTENTION: READ ALL CAUTIONS AND NOTES BEFORE AND AFTER REPROGRAMMING!

CAUTION:

- A poor connection between the vehicle and M-MDS and/or low voltage may result in abnormal termination and/or data corruption. A low battery voltage may cause a reprogramming failure resulting in unexpected ECU replacement.
- Make sure that the following connections are firmly connected, then DO NOT touch the VCM and DLC cable to prevent noise and a poor connection.
 - Between the vehicle-side connector and the DLC cable
 - Between the PC-side connector and the USB port of the PC
- When reprogramming with MDARS, power consumption and voltage fluctuation are greater than with IDS. Use the Power Supply mode in the Battery Management System (GR8) and connect an AC adapter to the PC to stabilize voltage fluctuation.




BEFORE REPROGRAMMING

NOTE:

- Turn off all electrical loads (i.e. A/C blower, audio system, rear defogger and headlights).
- Perform a self-test and verify no DTCs are stored. If any DTCs are stored, repair the concern and delete the DTCs.
- Disconnect any aftermarket accessories (non-genuine Mazda accessories).
- Terminate all programs other than MDARS on the PC. Running other programs may interfere with the MDARS performance, resulting in the PC freezing or other problems.
- Perform reprogramming with a proper internet connection. When using a wireless network, make sure the connection is strong.
- Make sure to keep enough free space on the PC's hard disc. Insufficient free space (less than 1 GB) may result in the PC freezing during reprogramming.
- 1. Connect the M-MDS to the vehicle.
- 2. Launch the Mazda Diagnostic And Repair Software (MDARS).

Page **3** of **10**

3. Turn the ignition on, then click "Start".



4. Select the "toolbox" tab.

ck Chec	Toobor						6
1000 (C							10
		100				404.)	
	.04	869,000	1000(19(.0))	0000,151,7		16	154
nc.	105	- 194	с. с. —	106	1990	140	- MAL
ioe	100	-	96	109			

Page 4 of 10

Bulletin No.: 09-037/19	Last Issued: 10/16/2019

5. Select Work Support group.

Transcom	🙆 - Koncolomban in 🖨 - Konne 🦉 - K	at 🐮 tv 🛢
2 X 1000		¥ A
La Lauregeet	Not Run	Bet
 Confirmation test for system operation 		
 On-domanfaelEiest 		
 Operational records 		
Sea Venicle History	Not 2ah	Bat

6. Select "Software update", then click "Run".

⊖ mazsa	🧿 noticas 🖓 vinc. Million Maladastas 🖄 🛤 🎽 car 🗄
u QuickChodi 🕺 Ioolbox	
ନ ଅ ଜ	¥
- Softwareupdate	
Software opdate	Not Rep Ran
+ Configuration	
+ ENGNE	
+ BRAKES	
+ TRANSMISSION/TRANSAULE	
+ RESTRUNTS	
+ SEATS	
+ SLOURTY AND LOOKS	
+ LIGHTING SYSTEMS	
+ WIPER/WASHER SYSTEM	

Page 5 of 10

7. Select the ECU to be reprogrammed.

Varias Caspinete and Repair Scillulary (MCVRS)		
9 measaa	а 🛑 🛤 😤 настаничальна 🏖 🛤 🍅 на	=
Cukathedi 🔊 iuulou 🖝 Software up- 🗙		
CU Reprogramming		^
Reprogrammable ECUs		
Search for an ECU		
rsc		
15C	>	
WCM.	>	
ESHL.	>	
PSRC PSRC	>	

8. Confirm the current and new software versions, then click "Next". **NOTE:** When reprogramming the BCM, two softwares will be shown.

Alada Dischools and Jupan Boltwark (HUMIS)		199	-	1	14 3 X
Omazoa	O m06112) 🖨 vie wintwa	MORE20451/8	2 10) 🕷 IV 🔳
m Quick Chara 🗙 Toobas 🗶 Software up 🗙					
ECU Reprogramming					^
Current Software					
Description	Current Version	Required Version	Size		
PCN	PA13-18882-A	FX.13-188K2-H	¥1	*	
				0	
					Nest


Page 6 of 10

9. Wait for the download, then click "Next".

NOTE: When reprogramming the BCM, downloading will occur twice.


() messae	O 0000222	🙈 ите лизанионаксонна		💌 ar 🗄
g (Junk Check 🔥 Joebear ● Software up- X				
ECU Reprogramming				
Downloading Vehicle Flash Files			Complete	
Downloading PCM PAJ3-188K2-F			Complete	
bownooding row roos sonar				
				Not

10. Read the screen instructions, then click "Next".



Page 7 of 10

11. Follow the instructions on the screen, then click "Next".



12. Wait for the reprogramming to complete. **NOTE:**

- The progress bar will stay at 90% for 30 seconds. This is not a failure.
- When reprogramming the BCM, this process will occur twice.

Were beauding a Brown St	A SAUDERIDES			S. MARRIED	
Updatingsoftwore				=	
1					
L	SurringPowen				
	Street Brand and Brand Science (Marting)			-	Test to a feature
	Updatingsofwere				=
	1				
		Rentry House 1	65		
	1				
	1				
					620
					100


Page 8 of 10

Bulletin No.: 09-037/19	Last Issued: 10/16/2019


AFTER REPROGRAMMING

NOTE:

• Select "Vehicle History" under "Collect Diagnostic Information", then click "Run".



• Confirm the reprogramming on the screen and save the screen copy as a record.



Page 9 of 10

WARRANTY INFORMATION

NOTE:

- This warranty information applies only to verified customer complaints on vehicles eligible for warranty repair.
- This repair will be covered under Mazda's New Vehicle Limited Warranty term.
- Additional diagnostic time cannot be claimed for this repair.

Warranty Type	А
Symptom Code	65
Damage Code	9W
Part Number Main Cause	5555-67-560
Quantity	0
Operation Number / Labor Hours:	XXR9JXFX / 0.2 Hrs.

After reprogramming, be sure to keep a copy of screen on M-MDS of the ECU FILENAME along with the repair order and warranty application sheet.

Page 10 of 10