

Technical Information

05/19 ENU WKA5


Service

WKA5 - Checking Fill Level Sensor for Water Spray System and Replacing it if Necessary (Workshop Campaign)

Vehicle type:	911 GT2 RS (991)
Model Year:	2018
Subject:	Fill level sensor for water spray system
Information:	There is a possibility that the float for the water spray system fill level sensor can stick at both the lowest and very top position due to unfavorable component tolerances on the affected vehicles.
	 If the float sticks at the lowest position, the warning message "Fill coolant reservoir for charge-air cooler - Visit workshop" will be displayed in the instrument cluster even though the reservoir for the water spray system is still sufficiently full. If the float sticks at the very top position, the reservoir will subsequently become empty and no warning message will be displayed. As a result, engine power will be reduced and the pump can be damaged.
Remedial Action:	Check the date of production on the water spray system reservoir and replace the fill level sensor if necessary.
Affected Vehicles:	Only the vehicles assigned to the campaign (see also PCSS Vehicle Information). There are 684 vehicles affected in the US and Canada

Installation

position:



Installation position of water spray system

- 1 Water spray system reservoir
- 2 Fill level sensor

Parts required

Parts Info: No parts are required for checking the date of production.

Parts required for **replacing the fill level sensor**:

Part No.	Designation	Qty.
00004330474	\Rightarrow Sensor module	1 ea.

Required tools

Tools:


Torque wrench, 2-10 Nm (1.5-7.5 ftlb.), e.g. V.A.G 1783 or equivalent - Torque wrench, 2-10 Nm (1.5-7.5 ftlb.)

Technical Information	Service		\mathbf{O}	
Technical information	05/19	ENU	WKA5	Ζ

Checking fill level sensor for water spray system and replacing it if necessary

- 1 Remove front luggage compartment trim panel \Rightarrow Workshop Manual '700519 Removing and installing trim panel for front luggage compartment'.
- 2 **Check date of production (DDMMYYYY)** on the water spray system reservoir and compare it with the table below ⇒ *Reading off date of production*. The date of production is shown on the **top of the reservoir**.

Attach a verifiable photo that clearly shows the date of production to the warranty claim.



Reading off date of production

Date of production	Next steps
Date of production on reservoir is 05092018 or later .	Fill level sensor does not have to be replaced . – End of measure – Continue with Step 4.
Date of production on reservoir is 04092018 or earlier .	The fill level sensor must be replaced . To do this, continue with Step 3 .

3 Replace fill level sensor.


3.2

3.3


3.4

4

3.1 Release and disconnect electric plug connection ⇒ Disconnecting electric plug connection -1- on the fill level sensor ⇒ Disconnecting electric plug connection -2-.



Disconnecting electric plug connection



Removing fill level sensor

Workshop Manual '700519 Removing and installing trim panel for front luggage compartment'.

Install front luggage compartment trim panel \Rightarrow

5 Enter the campaign in the Warranty and Maintenance booklet.

Unscrew fastening screws \Rightarrow *Removing fill level sensor* -1- and remove fill level sensor

Install new fill level sensor and secure it by

Connect and lock electric plug connection.

 \Rightarrow Removing fill level sensor -2-.

tightening the fastening screws. Tightening torque 8 Nm (6ftlb.)

AfterSales

Technical Information	Service			つ
	05/19	ENU	WKA5	Ζ

Warranty processing

Scope 1: Checking date of production on the water spray system reservoir - The fill level sensor does not have to be replaced.

Working time: Checking fill level sensor Includes: Removing and installing trim panel for front luggage compartment

Labor time: 41 TU

\Rightarrow Damage Code WKA5 066 000 1

Scope 2: Checking date of production on the water spray system reservoir and replacing fill level sensor.

Working time:				
Replacing fill level sensor Includes: Removing and installing trim panel for front luggage compartment Checking date of production			Labor time: 46 TU	
Parts requ	ired:			
000043304	174	Sensor module	1 ea.	
\Rightarrow Damage Code WKA5 066 000 2				

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2019 Porsche Cars North America, Inc.

AfterSales