

GROUP	NUMBER		
Interior	19-BD-008H		
DATE	MODEL(S)		
October, 2019	Santa Fe (TMa)		

## **Technical Service Bulletin**

## SUBJECT UPPER CONSOLE CUP HOLDER REPLACEMENT

#### **Description:**

This bulletin provides instructions on the replacement of a cup holder with retaining tabs which cannot stabilize a cup due to inner O-ring displacement.



Applicable Vehicles: Certain 2019MY Santa Fe (TMa) produced between 5/22/2018 – 3/18/2019

#### **Parts Information:**

PART NAME	PART NUMBER	QTY
Cup Holder Assembly		
	84670-S2000-4X	1

SUBJECT:

Warranty Information:

MODEL	OP CODE	OPERATION	OP TIME	CAUSAL PART	NATURE CODE	CAUSE CODE
Santa Fe (TMa)	90CA07R0	Cup Holder Replacement	0.3 M/H	84670-S2000-4X	114	ZZ4

**NOTE 1:** Submit Claim on Campaign Claim Entry Screen

**NOTE 2:** If a part is found in need of replacement while performing the repair for this TSB and the affected part is still under warranty, please submit a separate claim using the same Repair Order. If the affected part is out of warranty, submit a Prior Approval Request for goodwill consideration prior to performing the work.

#### Service Procedure:

1. Shift the vehicle into neutral.



Ensure that the engine is turned "OFF" with the parking brake engaged before proceeding.

2. Remove the gear knob & boot (A) by pulling them upwards.



#### SUBJECT:

#### UPPER CONSOLE CUP HOLDER REPLACEMENT

**3.** Remove the rubber mat (B).



 Using a flat head screwdriver or trim removal tool, remove the console upper cover (C).

# 

Avoid damaging the center console armrest and the surrounding trim components.



**5.** Press the lock pin and remove the console upper cover connector (D).

### NOTICE

Utilize care when separating the upper center console from the floor console. Avoid disconnecting the upper center console wiring harness from the floor harness.



### SUBJECT:

## UPPER CONSOLE CUP HOLDER REPLACEMENT

- 6. Remove the screws from each side of the cup holder (6 total), then remove and replace the cup holder with the new part.



**7.** Re-assemble the upper console assembly so the assembly points align with the floor console.

8. Re-assemble the gear knob & boot assembly. Ensure that it is fully seated and tested for function.



**9.** Service procedure is now complete.