

 <b>HYUNDAI</b> <b>Technical Service Bulletin</b>	<b>GROUP</b> <b>CAMPAIGN</b>	<b>NUMBER</b> <b>19-01-031H</b>
	<b>DATE</b> <b>OCTOBER 2019</b>	<b>MODEL(S)</b> <b>Santa Fe (NC)</b> <b>Veloster (FS)</b> <b>Elantra (MD)</b> <b>Azera (HG)</b>
<b>SUBJECT: STEERING ANGLE SENSOR RESET (SERVICE CAMPAIGN T4A)</b>		

**\* IMPORTANT**

**\*\*\* Retail Vehicles \*\*\***

Dealers must perform this Service Campaign on all affected vehicles whenever an affected vehicle is in the shop for any maintenance or repair.

When a vehicle arrives at the Service Department, access Hyundai Motor America's "Warranty Vehicle Information" screen via WEBDCS to identify open Campaigns.

**Description:**

Certain 2017-2018 MY Santa Fe (NC), 2016MY Veloster (FS), 2014MY Elantra (MD), and 2016-2017MY Azera (HG) vehicles may experience a warning lamp being illuminated intermittently when starting the engine after replacing the motor driven power steering (MDPS) column & housing. This bulletin describes the procedure to perform the steering angle sensor (SAS) reset using the GDS.



**Applicable Vehicles:** Certain 2017-2018MY Santa Fe (NC), 2016MY Veloster (FS), 2014MY Elantra (MD), and 2016-2017MY Azera (HG) vehicles.

**Warranty Information:**

Model	Op. Code	Operation	Op. Time	Causal Part	Nature Code	Cause Code
Santa Fe (NC) Veloster (FS) Elantra (MD) Azera (HG)	90C021R0	Steering Angle Sensor Reset	0.3 M/H	13381-08003	I3A	ZZ3


**NOTE 1:** Submit Claim on Campaign Claim Entry Screen

**NOTE 2:** If a part is found in need of replacement while performing Service Campaign T4A and the affected part is still under warranty, submit a separate claim using the same Repair Order. If the affected part is out of warranty submit a Prior Approval Request for goodwill consideration prior to performing the work.


Circulate To: General Manager, Service Manager, Parts Manager, Warranty Manager, Service Advisors, Technicians, Body Shop Manager, Fleet Repair

**Service Procedure:**


1. Connect the GDS or GDS-M.  
  
Select '**S/W Management**' on the screen.




2. Select '**Steering Angle Sensor Reset**'.



3. Review the overview then select 'OK'.




4. Check the conditions and select 'OK'.




- 5. Turn the ignition **OFF** and wait for 5 seconds. Then turn ignition back **ON**.


Select '**OK**' to complete the Steering Angle Sensor Reset function.




- 6. Next, from the S/W Management screen, select '**Steering Angle Sensor (SAS) Calibration**'.




7. Review the overview then select '**OK**'.



8. Review the overview then select '**OK**'.



9. Check the conditions and select '**OK**'.



10. Turn the ignition **OFF** and wait for 15 seconds. Then turn ignition back **ON**.

Select '**OK**' to complete the Steering Angle Sensor (SAS) Calibration function.

