
ATTENTION:

GENERAL MANAGER PARTS MANAGER CLAIMS PERSONNEL SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the hoxes provided, right.



© 2018 Subaru of America, Inc. All rights reserved.

SUBARU

NUMBER: 15-233-18R

DATE: 08/29/18

DATE: 11/15/19

QUALITY DRIVEN® SERVICE

SERVICE INFORMATION BULLETIN

APPLICABILITY: 2017-20MY Impreza

2017-20MY Crosstrek 2019-20MY Ascent 2019-20MY Forester

All above models with Harman 8" Touch Screen Display Audio or Navigation Equipped Audio Units

SUBJECT: Display / Touch Screen "Soft Keys" -Delayed

Response

INTRODUCTION:

This Service Information bulletin provides a procedure to use for addressing a customer concern of a delayed or slow response when using the soft keys on the touch screen of the audio / navigation head unit.

MATERIALS REQUIRED:

- A CLEAN (preferably new), soft micro-fiber cloth or towel
- Aerosol can of "Sprayway" -brand, Ammonia-free glass cleaner, available at most major retailers and home improvement stores

SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

IMPORTANT CAUTIONS:

- DO NOT spray the glass cleaner directly onto the display screen.
- Do NOT use a cotton towel or shop cloth which can easily scratch the display screen.
- Always confirm the protective film has been removed from the display screen.
- Apply the glass cleaner to the CLEAN micro-fiber cloth.
- LIGHTLY wipe the display screen to remove any dust or dirt until clean.

Continued...

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.



Bulletin Number: 15-233-18R; Revised: 11/15/19

Page 1 of 2

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

Bulletin Number: 15-233-18R; Revised: 11/15/19 Page 2 of 2