



Date: November 4, 2019
To: Audi Dealer Principal, Service Manager, Warranty Administrator, Sales Manager,
General Manager & Parts Manager
From: Audi Customer Protection
Subject: Upcoming Update 55K6 - Servicing Rear Lid Drive
Certain 2019 Audi A7 Vehicles

We would like to inform you of an upcoming Update, code 55K6.

What vehicles are affected?

There are 5,299 Audi vehicles in the U.S. and 818 vehicles in Canada affected by this Update. Check your daily campaign open inventory report or OMD for affected vehicles in your inventory.

What is the issue?

On Audi A7 vehicles manufactured within a specific period, the ball head on the rear lid drive may become detached.

What does the repair procedure involve?

Install new securing clip

When will the Update be available?

This Update will be visible in Elsa and ServiceNet on or about November 5, 2019.

Please refer to the Elsa campaign/action screen for confirmation of whether the Update applies to each specific vehicle. Additionally, this Update is posted on Elsa and ServiceNet for additional information and complete repair instructions.

Consistent with general Audi corporate policy governing Updates, Audi is not notifying consumers. (Updates differ from recalls and service actions; consumers are notified in writing of recalls and service actions.) Each vehicle should be completed when it is in to the dealer for maintenance or any other service visit. Dealer stock vehicles **cannot, however, be delivered** to consumers until the Update is completed.

To identify any vehicles in your inventory that are affected by this Update, please run the “New and CPO Inventory Open Campaign/Action Listing” report from the OMD Web system.

Dealers must ensure that every affected vehicle gets the update before delivery to consumers. Your effort is integral in reaching the highest quality expectations of Audi customers.

Thank you for your cooperation and assistance in this important matter.