



SERVICE BULLETIN

Classification: FA19-002	Reference: NTB19-105	Date: November 22, 2019
-----------------------------	-------------------------	----------------------------

CLICKING/POPPING NOISE FROM FRONT AXLE AREA DURING TAKE OFF/ACCELERATION AND/OR DECELERATION

APPLIED VEHICLES: 2019-2020 LEAF (ZE1)

IF YOU CONFIRM

A clicking or popping noise is coming from the front axle area during take off/acceleration and/or deceleration.

ACTION

Before performing diagnostic procedures, torque the lug nuts for all four (4) wheels to 113N•m (12kg-m, **83 ft-lbs**), in a diagonal pattern.

- If the clicking/popping noise is still present after torquing the lug nuts, refer to the ESM for further diagnostic information.




Figure 1

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

CLAIMS INFORMATION

Submit a Primary Part (PP) type line claim using the following claims coding:

DESCRIPTION	PFP	OP CODE	SYM	DIA	FRT
Check Torque on Wheel Nuts (All)	(1)	PX92AA	ZE	32	0.2

(1) Reference the electronic parts catalog and use the Wheel Road Nut (40224-*****) as the Primary Failed Part (PFP).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 22, 2019	NTB19-105	Original bulletin published

