

Special Service Message

NOTE: A Special Service Message is a formal communication issued by Jaguar and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Jaguar technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 74636 - Vehicle only accepts charge up to 94% then IPC shows charge completed

Models : I-Pace / X590

Engineer Gál Attila

Name :

Last 29 NOV 2019 07:10:28

Modified :

Category : Electrical

Symptom : 203000 Basic Electrical

Content :ISSUE:

Vehicle only accepts charge up to 94% then IPC shows charge completed.

This SSM is only applicable for non-China market vehicles.

CAUSE:

When PATHFINDER routine 'Cell Supervisory Circuit (CSC) Replacement ', failed to complete with error message: 'Failed to assign Cell Supervisory Circuit (CSC) unique identification'. Vehicle will only accept charge up to 94%.

ACTION:

CAUTION: This procedure requires a minimum of Pathfinder 261 installed or later.

1. Connect the JLR approved battery support unit.
2. Connect the JLR approved diagnostic equipment to the vehicle and begin a new session.
3. Follow the JLR approved diagnostic equipment prompts.

- Select 'ECU Diagnostics'.
- Open the BECM menu
- Select ECU Functions.
- Complete the routine 'Cell Supervisory Circuit (CSC) Replacement'.

5. When all of the tasks are complete, exit the session.
6. Disconnect the JLR approved diagnostic equipment

and the JLR approved battery support unit.

Jaguar Land Rover Limited 2000 - 2019 (Rel. 2675)