

**** SOLUTION ****

Title	Diagnostic Trouble Code (DTC) P20EE - SCR NOx Catalyst Efficiency Below Threshold (Bank 1) - US17+OBD2019 Emissions, Model Year 2020 ONLY
-------	--

Mack Models

Mack Model	AN - Anthem , CHU - Pinnacle, Axle back , CXU - Pinnacle, Axle front , GR - Granite , GU - Granite , PI - Pinnacle
-------------------	--

Volvo Models

Volvo Model	VN , VNL , VNR , VNX , VAH , VHD
--------------------	----------------------------------

Emission Standard

Emission Standard	US17+OBD19
-------------------	------------

Engine family

Engine family	11L Engine , 13L Engine , MP7 , MP8
---------------	-------------------------------------

**** SOLUTION ****

Cause	Trucks built for emissions level US17+OBD19 (Model year 2020) and equipped with a one-box exhaust aftertreatment system (DPF, DOC and SCR are contained in one unit) have shown a higher than normal occurrence of fault code P20EE logged in the field.
--------------	--

Affected vehicles have been observed having large urea crystal buildup starting from the DEF dosing valve. When applicable SCR mufflers are evaluated following removal of the DEF crystals, the SCR functions as good as a new component.

Solution**Return Visit**

If the vehicle has been in for this issue previously an eService case should be started for further assistance **AFTER** verifying that the same problem exists.

The eService case MUST INCLUDE:


- The CBR Diagnostic Session number or this Solution number.
- A thorough description of the problem.
- The vehicles previous history and what was done to resolve the issue on previous visits (This solution MUST have been performed previously if a case is being opened!).
- A complete DTC readout from the time of the vehicle's arrival.

First Visit

1. Verify the chassis emissions level and ensure that the vehicle is within the applicable

range for this solution.

Details can be found in the Product Details box on the Product tab in PTT as seen below:



2. Remove the DEF dosing valve and inspect for crystal buildup.

An example of expected crystal buildup can be seen below:



- 2.1. If crystal buildup is similar to that shown in the picture above: Continue to Step 3.

2.2 If there are no crystals present, or the crystal accumulation is light with small crystals: Proceed to and complete solution [K65527708](#).

3. Remove the DPF (Tear Drop) cover and clean the crystal accumulation out of the pipes.

3.1. With a damp cloth, wipe off the DEF dosing valve and mixing vanes.



4. Once the inside of the muffler is clean, Install new gaskets and V-clamps clamps for the tear drop cover.

5. Re-install the cover.

6. Remove and discard the insulator (gasket) from the dosing valve. The part is highlighted in the picture below.



7. Re-install the DEF dosing valve WITHOUT a new insulator. Make sure to use a new sealing plate and new mounting screws (one time use parts).



8. Clear fault codes.

9. Perform a Sulfur Regeneration. This will complete the cleaning of the SCR.

10. Release the vehicle.

This is a temporary containment for this issue. This solution will be updated when more information is available.

Internal comments (FO)	This is a containment. If a truck has P20EE without urea crystals or if a truck returns with crystallization even after containment please contact Nataraj Bhat/ John Whelan for additional analysis.
Temporary solution	Temporary solution
Solution visibility	Dealer distribution

Function(s)/component(s) affected

Function affected	SCR , DEF Dosing
-------------------	------------------

Function Group

Function Group	254 catalytic converter; exhaust emission control equipment , 2584 Dosage Valve; Injector
----------------	--

Customer effect

Main customer effect	regeneration , fault code/display
----------------------	-----------------------------------

Fluid implicated	Diesel Exhaust Fluid (DEF)
------------------	----------------------------

Fault Codes And Error Codes

OBDDII Diagnostic Trouble Codes (P, U, B Format)	P0422-00 , P103C-00 , P20EE-00 , P225C-00
---	---

Administration

Author	UT0031H
--------	---------

Dealer ID	UT0031H
-----------	---------

Last modified by	RU4469V
------------------	---------

Creation date	16-10-2019 19:10
---------------	------------------

Date of last update	13-11-2019 20:11
---------------------	------------------

Review date	16-12-2019 00:12
-------------	------------------

Status	Published
--------	-----------

NA_Reviewer	UT0031H
-------------	---------

UNCONTROLLED COPY. Printed document is for temporary use only and should not be retained.