

Offboard Diagnostic Information System Service (ODIS Service) Number: VOS-19-34

Subject: Software Version Update, Enhancements and Fixes Date: Dec. 2, 2019

#### Supersedes VOS-19-32 due to new diagnostic content version.

The following ODIS Service software versions are available for download.

Current ODIS Service Software Versions	
Application: <b>V5.1.6</b>	Diagnostic Content: <b>V2.39.13</b>

## Key Fixes/Enhancements for Diagnostic Content: V2.39.13:

## 7P · Touareg 2010 – 2017, CGRA 3.6 L FSI / 206kW

Battery history data test J533\_X\_1\_0712\_11\_Historiendaten\_00011 is not available in data bus on board diagnostic interface Functions.

## BW - Tiguan 2018 – 2019

P020100: Cylinder 1- Injector Circuit

N30\_X\_1\_0916\_11\_X\_X\_OBD1\_XX\_FSB\_OBD1\_N30\_00011 instructs technician to install test harness VAS 5571 to wiring harness for fuel injector, leaving injector unplugged, induce a short circuit to ground.....Start engine and let it idle.

 In order to access the fuel injectors on the vehicle the intake manifold must be removed making starting of engine not possible.

#### CA/CM Atlas 2018 – 2019

P21A100: Cylinder 6 Air-Fuel Ratio Imbalance SYS\_X\_1\_0617\_11\_X\_X\_CIL\_FSB\_00000 test ends with Program malfunction CKC01 - Send feedback to support.



(cont.)

## 5C · Beetle 2012 – 2018, CPRA 1.8l Simos / 125 kW

P050600: Idle Control System RPM Lower than Expected test SYS\_X\_1\_0616\_X\_X\_GMS\_FSB\_00000 is inconclusive. Test states new test plans and DTCs to be added in DTC memory entry.

- o The adaptation of the Throttle Valve Control Module -J338- was not successful.
- o No test plan was added automatically and no new DTC memory entry was be added.

## 16 - Jetta 2011 – 2018, CJAA 2.0I TDI CR / 103 kW

P048B00: exhaust pressure control valve position sensor/switch circuit

J883\_X\_1\_0212\_11\_TDI01\_X\_Abgasklappe\_00011 after verifying wiring voltage, test ends without stating what component to replace or the test next steps.

## 5C - Beetle 2012 – 2018, CBFA 2.0l Motronic / 147 kW

P2431: Secondary Air Injection System Air Flow/Pressure Bank 1 Sensor Circuit Range/Performance G609\_5KU26CBFA\_1\_0409\_66\_00066 secondary air system pressure MVB displays engine RPM instead of pressure.

The test should be comparing the actual pressure at secondary air injection sensor 1 with the pressure readings at Charge Air Pressure Sensor -G31 and the Barometric Pressure (BARO) Sensor -F96. Deviation between the sensors max. 60 mbar.

## 7P - Touareg 2010 – 2017, CNRB 3.0l TDI-CR / 176kW

ECM DTC P159200: Altitude sensor signal/charge air pressure sensor implausible ratio test G31 X 1 0212 11 TDI01 X Ladedruckgeber 00011 is incomplete.

o Test ends after the wiring test and does not provide any next steps.



(cont.)

## 7P · Touareg 2010 – 2017, CNRB 3.0l TDI·CR / 176kW

P03A500: Cylinder 2 Pressure Too High test

GXXX\_7P\_23\_CATA\_1\_0610\_11\_Brennraumdruckgeber\_00011 malfunctions and does not complete.

o The user is consistently kicked out while performing the test steps.

### CA/CM Atlas 2018 – 2019

U123600: No communication in driving profile rotary switch

E735\_X\_1\_0619\_11\_Taster\_fuer\_Fahrprofilauswahl\_00000 diagnoses and replaces E735 - Driving Profile Selection Button.

o The vehicle is equipped with Driving Profile Selection Control Head -E881 and not E735 - Driving Profile Selection Button.

## 5C · Beetle 2012 – 2018, CPRA 1.8l Simos / 125 kW

P102F00: Torque limitation due to fuel pressure SYS24\_X\_1\_1112\_11\_X\_X\_Kraftstoffsystem\_00011 test step checking fuel rail pressure displays an incorrect value for the actual pressure in rail: 0.0 bar.

Test could not proceed and was cancelled due to error message: The value Fuel Rail Pressure for the request parameter Record Data Identifier could not be entered.

## A3 · Passat/New Midsize Sedan 2011 – 2017, CVCA 2.0I TDI SCR / 110 kW

No test plan created for P040C00: Exhaust Gas Recirculation Temperature Sensor "A" in the current test plans.



(cont.)

## 16 - Jetta 2011 – 2018, CNLA 1.4l TFSI Hybrid / 110 kW

DTCs P030000: Random/Multiple Cylinder Misfire Detected and P030100: Cyl.1 Misfire Detected test SYS\_X\_J623\_1\_1112\_11\_X\_X\_Aussetzererkennung\_00011 states that Misfire detection is: inactive and Misfires 0 were detected.

Vehicle is actively misfiring and MIL is flashing. Engine MVB function
 SYSCNLAJ623\_1\_0212\_66\_14TFS01\_Messwerte\_lesen\_00066 shows an active misfires on cylinder 1.

## • 16 - Jetta 2011 – 2018, CPRA 1.8 Simos / 125 kW

P085000: Park/Neutral Switch Input Circuit test SIG27\_X\_J623\_1\_1112\_11\_Startersteuerung\_00011 ends before checking the function of the park/neutral switch.

• General translation errors.