

MODEL

SIB 12 28 19

THE MIL MAY BE ILLUMINATED BY ERRONEOUS VALVETRONIC FAULTS

2019-11-15

| <b>E-Series</b> | Model Description          | Production Date        | Affected Engines |
|-----------------|----------------------------|------------------------|------------------|
| G05             | X5 Sports Activity Vehicle | Starting June 15, 2019 | N63M and N63B    |
| G06             | X6 Sports Activity Coupe   | Starting July 1, 2019  | N63B             |
| G07             | X7 Sports Activity Vehicle | Starting June 15, 2019 | N63M and N63B    |
| G14             | 8 Series Convertible       | Starting June 15, 2019 | N63B             |
| G15             | 8 Series Coupe             | Starting June 15, 2019 | N63B             |
| G16             | 8 Series Gran Coupe        | Starting June 15, 2019 | N63B             |

# **SITUATION**

One of the following faults may be stored in the digital motor electronics (DME), either as part of diagnosing a different issue; and-or an illuminated malfunction indicator lamp (MIL).

| Fault code | Control module | Fault code text   |  |
|------------|----------------|---|--|
| 13380A     | DME            | Valvetronic output stage, component protection: Overload current during control operation |  |
| Or:        |                |   |  |
| 13380A     | DME            | DME, internal fault, Valvetronic output stage: Diagnosis during control operation         |  |

Note: The fault code text is dependent on the current vehicle I-Level.

Only vehicles with a factory I-level below S18A-20-07-500 and above S18A-19-07-500 are affected.

This situation is not associated with any drivability complaints.

# CAUSE

An unfavorable DME diagnostic calibration may cause the fault code to be erroneously stored. In rare circumstances, this may cause the MIL to illuminate.

### **CORRECTION**

Evaluate the fault environmental conditions, then follow the recommended procedure.

### **PROCEDURE**

Determine the vehicle's current I-level by using AIR, or the Key reader-ISPA NEXT application.

If the I-level is below S18A-20-07-500 and above S18A-19-07-500, then:

1. Perform a vehicle test (MIL is **not** illuminated, as part of another repair) and evaluate the fault code environmental information for 13380A.

2. If the "Supply voltage load at TC" is 8 volts or more:

- Perform diagnosis using the latest version of ISTA
- 3. If the MIL is **not** illuminated:

- Ignore the fault and clear the fault memory
- 4. If the MIL is illuminated:
  - Perform the Valvetronic activation test plan (ABL AT1214\_BX8\_VVAK)

Path to Valvetronic activation test plan:

- Drive
- Engine Electronics
- Valve gear
- Valvetronic
- Valvetronic activation

# WARRANTY INFORMATION

This Service Information bulletin provides technical, diagnostic and repair-related information.

#### **Eligible and Covered Work-Repairs**

When the ISTA diagnostics and related test plans are used to repair a verified defect in materials or workmanship as described above, the repair procedure information provided in this bulletin is covered under the terms of the New Vehicle Limited Warranty and the applicable Emissions Warranty that applies to BMW Passenger Cars and Light Trucks.

To submit a claim, please following the established and applicable warranty policy and procedures (Labor-Part-Sublet – bulk materials) that apply to the repair being performed.

Refer to AIR for the corresponding defect code, flat rate labor operations and the flat rate unit (FRU) allowances (including diagnosis with separate punch times).