



Subject:

EFFECTIVE IMMEDIATELY - SUSPENSION OF MSP56 - MODULE REPROGRAMMING TO PREVENT KEYS FROM BEING LOCKED INSIDE VEHICLE

∴

Last Issued: 12/16/2019

DESCRIPTION

Effective immediately, MSP56 has been suspended until further notice. MSP56 was launched to prevent 2019 Mazda3 5dr vehicles from locking, if the keys are left inside the vehicle. There have been reports of Body Control Module (BCM) failures during the update process, and in the worst case scenario, a loss of vehicle mileage in the odometer.

Until further notice, DO NOT update or reflash the Body Control Module (BCM) or LFU using MDARS unless directed by the Technical Hotline. Claims will not be accepted with repair dates beyond 12/16/2019.

If the keys are accidentally locked in the vehicle because MSP56 was not performed, the liftgate opener will still open the liftgate and the keys can be accessed through the rear hatch.

We apologize for any inconvenience the suspension of MSP56 may cause you and your customers.

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.