

Y1A Interim Procedure to Restore Function Enabling Using PT3G

Vehicles Affected

Model	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	2020	Y1A	N/A	N/A

Revision History

Revision	Release Date	Changes
0	December 20, 2019	Original document

Condition

The following work will require function enabling for the Taycan:

- Replacing the gateway
- Enabling Functions on Demand (FoD)

Service Information

Programmed function enabling is not available for Taycan on PT3G release 39.000.000. Therefore, for the first few weeks after Taycan launch (until this feature is added to the tester), the typical procedure for activating functions on the vehicle will not work. Instead, PCNA will provide a workaround.

Prerequisite: You must use PT3G release 39.000.x.

Preparatory steps

1. Optional: If it is necessary to (1) replace the vehicle gateway or (2) commission component protection in the gateway, perform that work first.
2. Create a pre-work VAL on the PT3G and make sure it is uploaded to the PIWIS server.
Note: If you performed the optional work above (replacing the gateway or commissioning component protection in the gateway), you must create and send a VAL from after performing that work.
3. Submit a PTEC-TLAR and request function enabling codes
4. Your PCNA dealer technical support team will provide further instructions

Warranty

Please claim labor according to the typical process for similar work.

Search Items

Taycan; Y1A; warranty

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.