



TECHNICAL SERVICE BULLETIN

3.5L EcoBoost - Stability Control, Traction Control And/Or Advance Trac® Warning In The IPC With DTC C0051 Stored In The ABS Module

19-
2394
20
December
2019

Model:

Ford 2018-2019 F-150	Engine: 3.5L EcoBoost
--------------------------------	-----------------------

Issue: Some 2018-2019 F-150 vehicles built at Dearborn Truck Plant on 17-Jul-2017 and through 26-Jul-2019 or Kansas City Assembly Plant on 14-Aug-2017 and through 28-Jul-2019 equipped with a 3.5L EcoBoost engine, 3675 mm (145 in) wheelbase, XL/STX trim package, and max trailer tow package (towing pack 1) may exhibit a stability control, traction control and/or Advance Trac® warning message in the instrument panel cluster (IPC) message center with diagnostic trouble code (DTC) C0051:54 and/or C0051:64 stored in the anti-lock braking system (ABS) module. This maybe due to one or more software parameters in the ABS module. To correct the condition, follow the Service Procedure steps to reprogram the ABS module.

Action: Follow the Service Procedure steps to correct the condition on vehicles that meet all of the following criteria:

- 2018-2019 F-150
 - Built at Dearborn Truck Plant on 17-Jul-2017 and through 26-Jul-2019
 - Built at Kansas City Assembly Plant on 14-Aug-2017 and through 28-Jul-2019
- 3675 mm (145 in) wheelbase
- 3.5L EcoBoost engine
- XL/STX trim package
- Max trailer tow package (towing pack 1)
- Illuminated stability control and traction control indicator and/or service Advance Trac® warning message with DTC C0051:54 and/or C0051:64 stored in the ABS module

Warranty Status: Eligible under provisions of New Vehicle Limited Warranty (NVLW)/Service Part Warranty (SPW)/Special Service Part (SSP)/Extended Service Plan (ESP) coverage. Limits/policies/prior approvals are not altered by a TSB. NVLW/SPW/SSP/ESP coverage limits are determined by the identified causal part and verified using the OASIS part coverage tool.

Labor Times

Description	Operation No.	Time
2018-2019 F-150 3.5L EcoBoost: Retrieve DTCs And Reprogram The ABS Module (Do Not Use With Any Other Labor Operations)	192394A	0.3 Hrs.

Repair/Claim Coding

Causal Part:	3504
Condition Code:	04

Service Procedure

NOTE: This repair is only applicable on vehicles equipped with specific option content built within a specific date range. The ABS software update will not be available on vehicles that do not meet the required criteria.

1. Reprogram the ABS module using the latest software level of the appropriate Ford diagnostic scan tool.

© 2019 Ford Motor Company

All rights reserved.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford or Lincoln dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.