


MIL ON With DTC P013A

Service Category Engine/Hybrid System

Section Engine Control

Market USA

Lexus Supports
ASE Certification 

Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2020	NX300H	

Introduction

Some 2020 model year NX300h vehicles equipped with a 2AR-FXE engine may exhibit a MIL ON condition with Diagnostic Trouble Code (DTC) P013A (Oxygen Sensor Slow Response – Rich to Lean Bank 1 Sensor 2). This condition may be caused by a leak from the exhaust manifold to front pipe donut gasket. Follow the Repair Procedure in this bulletin to address this condition.

Production Change Information

This bulletin applies to vehicles produced **BEFORE** the Production Change Effective VIN shown below.

MODEL	PLANT	DRIVETRAIN	PRODUCTION CHANGE EFFECTIVE VIN
NX300h	Tahara	AWD	JTJGJRDZ#L5006704

Warranty Information

OP CODE	DESCRIPTION	TIME	OFF	T1	T2
170101	R & R Exhaust Manifold Donut Gasket	0.7	17451-28040	8A	57

APPLICABLE WARRANTY

- This repair is covered under the Lexus Comprehensive Warranty. This warranty is in effect for 48 months or 50,000 miles, whichever occurs first, from the vehicle's in-service date.
- Warranty application is limited to occurrence of the specified condition described in this bulletin.

MIL ON With DTC P013A

Parts Information

PART NUMBER		PART NAME	QTY
PREVIOUS	NEW		
17451-28070	17451-0D150	Gasket, Exhaust Pipe (Donut Gasket)	1
–	90917-06072	Gasket, Exhaust Pipe	1

Required Tools & Equipment

REQUIRED EQUIPMENT	SUPPLIER	PART NUMBER	QTY
Techstream ADVi*	ADE	TSADVUNIT	1
Techstream 2.0		TS2UNIT	
Techstream Lite		TSLITEPDLR01	
Techstream Lite (Green Cable)		TSLP2DLR01	

*Essential SST.

NOTE

- Only ONE of the Techstream units listed above is required.
- Software version 14.30.022 or later is required.
- Additional Techstream units may be ordered by calling Approved Dealer Equipment (ADE) at 1-800-368-6787.

Repair Procedure

1. Does the vehicle exhibit a MIL ON condition with Diagnostic Trouble Code (DTC) P013A (Oxygen Sensor Slow Response – Rich to Lean Bank 1 Sensor 2)?
 - **YES** — Continue to step 2.
 - **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.
2. Check for a leak from the exhaust manifold to front pipe donut gasket.

HINT

Blow compressed air around the donut gasket and look for a change in B1S2 O2 sensor readings in Techstream while the vehicle is in "Maintenance Mode."

Do the B1S2 O2 sensor readings change while blowing compressed air around the donut gasket?

- **YES** — Continue to step 3.
- **NO** — This bulletin does NOT apply. Continue diagnosis using the applicable Repair Manual.

MIL ON With DTC P013A

Repair Procedure (continued)

3. Replace the affected donut gasket between the exhaust manifold and the front pipe.
 - A. Remove the front pipe and gaskets.

Refer to TIS, applicable model and model year Repair Manual:

 - 2020 NX300h:
Engine/Hybrid System – Intake/Exhaust
[“2AR-FXE Intake / Exhaust: Exhaust Pipe: Removal”](#)
 - B. Reuse the front pipe and install NEW front pipe gaskets.

Refer to TIS, applicable model and model year Repair Manual:

 - 2020 NX300h:
Engine/Hybrid System – Intake/Exhaust
[“2AR-FXE Intake / Exhaust: Exhaust Pipe: Installation”](#)
4. Clear ANY DTCs and test-drive the vehicle to confirm the condition is no longer present.