Торіс	91-18-15TT - Apple Car-Play Initialization Failure	
Market area	United States 444 Volkswagen of America, Inc. (6444)	
Brand	Volkswagen	
Date	November 16, 2018	

Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN. TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Apple Car-Play Connection Initialization Failure

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	2016-2019	All	All	All	All

Technical Background

Apple Car-Play will not initialize after connection is made.

Service

Beginning with iOS 11.4.1, customers attempting to use Car-Play may experience an initial failure of the feature to initialize after plugging in their device. This condition will occur if the device has not been unlocked for one hour prior to connecting to the vehicle. Simply unlocking the device will then permit normal operation.

However, it is possible to prevent this initial lockout from occurring by performing the following steps in the device:

- Enter the Settings menu in the iOS device.
- Select Touch ID & Passcode.
- Enable (toggle on) the USB Accessories feature.



Additional Information

Revision History						
Revision Number	Released Date	Reason For Update				
2052993/1	11/16/18	Original publication.				

© 2018 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.