



Technical Service Bulletin

01 MIL on, DTC P050A00 and/or P050700 stored in the ECM

01 20 41 2053040/2 January 9, 2020. Supersedes Technical Service Bulletin Group 01 number 18-91 dated November 21, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6	2018	All	Not Applicable
A3, Q3, and TT	2019 - 2020	All	Not Applicable

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Added A3, Q3, and TT) Revised <i>Condition</i> (Added DTC)
1	11/21/2018	Initial publication

Customer states:

- MIL on.

Workshop findings:

One of the following DTCs is stored in the engine control module (ECM), J623 (address word 0001):

- **DTC P050A00** (Cold Start Idle Air Control System Performance).
- **DTC P050700** (Idle speed too high).

Technical Background

On some of the vehicles, it is possible that the throttle body is unable to lower the engine idle during catalyst warm-up. This is caused by incorrect basic settings for the throttle body stored in the engine control module, not due to a component defect.

Production Solution

Not applicable.



Technical Service Bulletin

Service

1. Erase the DTC stored in the ECM, J623 (address word 0001).
2. Using Guided Fault Finding, perform the test plan for throttle body adaption.



Note:

Do not replace the throttle body.

Warranty

Claim Type:	<ul style="list-style-type: none">• 110 up to 48 Months/50,000 Miles.• G10 for CPO Covered Vehicles – Verify Owner.• If the vehicle is outside any warranty, this Technical Service Bulletin is informational only.		
Service Number:	2434		
Damage Code:	0012		
Diagnostic Time:	GFF – Checking DTCs, clearing DTCS, and adapting the throttle body	0150 0000	Time stated on the diagnostic protocol (Max 50 TU)
	Road test before service procedure	No allowance	0 TU
	Road test after service procedure	No allowance	0 TU
Claim Comment:	As per TSB #2053040/2		

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Additional Information

All part and service references provided in this TSB (2053040) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of



Technical Service Bulletin

Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.