



Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.

TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Applicable Vehicles					
Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas, Tiguan LWB	2018-2019	All	All	All	All

Revision Table			
Instance Number	Published Date	Version Number	Reason For Update
2058406/1	01/24/20	55-20-01TT	Original publication.

Technical Background

Rear lid may open a few inches and stop, not able to set basic settings; rear lid may lose basic settings.

Service

With ODIS under Address word 6D Rear Lid Electronics:

1. Search "Rear" (Fig.1) in MVB information under control module OBD function.
2. Select "Status of rear lid lock", move to the right column to view and expand the values monitoring "Safety catch".
3. Verify the value changes for actual position of the rear lid for open & closed positions.

If it's found that the value for Safety catch remains unchanged (Fig.2) for rear lid operation, replacement of rear lid latch is required.




Figure 1



Figure 2



Additional Information

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.