

**Symptom Inside: Maximum Speed Porsche InnoDrive Max. 18 mph (30 km/h):
Re-program Central Computer using SD card (SY 146/19)**

Model Line: **Panamera (971)**

Model Year: **2018**

Equipment: **ACC High with Innodrive (I-no. 3V1)**

Subject: **Central computer**

Symptom: After restarting the vehicle several times, the configured speed limit in the Porsche InnoDrive (PID) is set back to max. 18 mph (30 km/h) sporadically.

Cause: This fault type can occur due to software programming in the central computer.

Remedial Action: Re-program the central computer using an SD card, see *⇒Workshop Manual '915225 Programming central computer data update'*.



Information

- With the current software version, the configured speed limit is reset to the delivery status 80 mph (130 km/h).

Date of Introduction: The updated software version has been installed on the central computers in production since November 5, 2018.

Parts Info:	Part No.	Market	Designation	Qty.
	971919360AA	NAR	⇒ SD card	1 ea.

- Tools:
- **Battery charger** with a current rating of **at least 90 A**, e.g. **VAS 5908 - Battery charger 90A or equivalent**.
 - **9900 - PIWIS Tester 3** with installed PIWIS Tester software **version 38.900.000** (or higher)

Invoicing

Invoicing: For documentation and warranty invoicing, enter the labor operation and PQIS coding specified below in the warranty claim:

APOS	Labor operation	I No.
91522552	Programming central computer (21 TU)	

PQIS coding:

Location (FES5)	91520	Central computer
Damage type (SA4)	4000	electrical faults

References: ⇒ *Workshop Manual '915225 Programming central computer data update'*

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2020 Porsche Cars North America, Inc.