

40 Rumbling/creaking noises from front of vehicle while driving - A6, A7, and A8

40 20 00 2048266/7 February 6, 2020. Supersedes Technical Service Bulletin Group 40 number 18-90 dated December 13, 2018 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A7, and A8	2015 - 2018	All	Not Applicable

Condition

REVISION HISTORY					
Revision	Date	Purpose			
7	-	Revised header (Updated models)			
		Revised Technical Background (Updated information)			
		Revised Service (Updated information)			
		Revised Warranty (Updated information)			
		Revised Required Parts and Tools (Added table)			
6	12/13/2018	Revised Production Solution (Updated dates)			
5	10/04/2018	Revised Warranty (Updated Service Number and Labor Operations)			

Customer states:

• They can hear rumbling, squeaking, creaking or similar noises from the front of the vehicle while driving on uneven roads. The noises can possibly be heard and felt in the footwell or behind the dash panel.

Workshop findings:

• The noises can be reproduced.



Technical Background

The noises can be generated on the lower left guide in the area of the hydro-bush. (Figure 1 – Position 7 and 8)




Figure 1. Lower left guide.

Parts such as the coupling rod (Figure 2 – Position 30) are usually replaced by mistake, presenting no problems.

The noises from the guide link can be transmitted into the vehicle interior by the connection of the sub frame on the body and are noticeable in the foot well.




Figure 2. Coupling rod.

Production Solution

Not applicable.



Service

Replace the hydro-bush on the guide link in pairs. (Figure 1 – Position 8) according to the instructions in Elsa at Repair Manual, Chassis >> Suspension, Wheels, Steering >> 40 Front Axle >> Lower Control Arm and Ball Joint >> Guide link bonded rubber bushing, Removing and Installing.

If repeat repairs are necessary and the hydro-bush has already been replaced (pressed out/in), the complete guide link has to be replaced (Figure 1 – Position 7) according to the instructions in Elsa at Repair Manual, Chassis>>Suspension, Wheels, Steering>>40 Front Axle>>Lower Control Arm and Ball Joint>>Guide Link, Removing and Installing.



Tip:

- Please precisely locate the source of the noise with acoustic testers.
- · Check the repair history for repeated repairs.

Warranty

Claim Type:	• 110 up to 48 Months/50,000 Miles.				
	 G10 for CPO Covered Vehicles – Verify Owner. If vehicle is outside any warranty, this Technical Service Bulletin is informational only. 				
Service Number:	4012				
Damage Code:	0020				
Labor Operations:	1 Wheel remove + reinstall	4405 1900	See SRT		
	2 Wheels remove + reinstall	4405 2000	See SRT		
	1 Lower guide link remove + reinstall	4016 1950	See SRT		
	2 Lower guide links remove + reinstall	4016 2050	See SRT		
	Replace guide link mounting	4012 5550	See SRT		
	Replace 2 guide link mounting	4012 5650	See SRT		
Diagnostic Time:	GFF	No allowance	0 TU		
	Road test prior to service procedure	0121 0002	10 TU		
	Road test after service procedure	0121 0004	10 TU		



Claim Comment:	As per TSB #2048266/7
Glaini Gommont.	7.6 por 165 #26 16266/1

All warranty claims submitted for payment must be in accordance with the *Audi Warranty Policies and Procedures Manual*. Claims are subject to review or audit by Audi Warranty.

Required Parts and Tools

Always check with your Parts Department and/or ETKA for the latest information and parts bulletins.				
Part Number	Part Description	Quantity		
See ETKA	Hydro-Bush	02		
See ETKA	Guide Link (only if Hydro-Bush has been replaced previously)	01 or 02		
See ETKA	Fasteners, Bolts, Nuts, and Screws as needed per the Repair Manual	See ETKA/ELSA		

Additional Information

All parts and service references provided in this TSB (2048266) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.